

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel under contract 260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 308)

Set 1/4 sec. post; from which
An Alder, 16" dia., bears N.10°W., 32 lks.
A Cedar, 8" dia., bears S.63 1/2°E., 23 lks.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12497)

Point for the 1/4 sec. cor. of secs. 27 & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

1/4
S 28 | S 27
1953 from which

A maple, 26" dia., bears S.43 1/4°E., 30 lks., mkd: 1/4 S27 BT.
A cedar, 36" dia., bears N.46°W., 33 lks., mkd: 1/4 S28 BT.
The E peak of roof of shake house, bears N.24°W.

The 1/4 sec. cor. is located about 1 1/2 chs. E of a ravine, course N

Fd. Ok BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO recs Vol. 37 Pg 15387-8) - Fd. BC & 2 BTs, Rescribe NW BT on new blaze.

Fd. & used on BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor under Group #1090, surveyed April/May 1982 - (DCSO records Vol. 45 Page(s) 17457)

Les Roberts - Ted Baker - 3/13/1986 - C.S. File 62/30-6

Found - 1953 GLO brass cap set firmly in ground.
32" Maple, S.46°E., 21.3' (scar vis) 1953 BT rec.
S.43 1/4°E., 19.8'
48" Cedar, N.46°W., 22.7' (no marks) 1953 BT rec.
N.46°W., 21.8'

Set - Set additional corner R.P's because of planned logging activity in near future.
8" spike in base of 48" Cedar, bears N.45°W., 21.3'
8" spike in side of f18" Maple stump. Spike bears S.79°E., 36.9'

Note - Corner lies on steep East slope about 350' West of West Branch Road.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Les Roberts - 11/26/1986 - C.S. File 63/50-16

Found - 1953 GLO survey brass cap up-rooted by recent logging.

32" maple stump, S.46°E., 21.3 ft. (scar vis.) 1953 BT. (Rec. S.43¼°E., 19.8 ft.)

48" cedar stump, N.46°W., 22.7 ft. (no marks) 1953 BT. (Record N.46°W., 21.8 ft.)

8" spike in top of 48" cedar stump, N.45°W., 21.3 ft. to spike.

8" spike in side of 18" maple stump, S.79°E., 36.9 ft. to spike.

Set - Re-set 1953 GLO brass cap firmly in ground using distances of 21.3 ft. and 36.9 ft. from 8" spikes set in 3/13/86. Buried purple magnetic marker under iron pipe.

Set metal fence post, with survey attention sign wired to, beside brass cap.

Corner lies on steep East slope about 350 ft. west of West Branch Road

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23100)

The ¼ sec. cor. of secs. 27 & 28, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, in a collar of stone, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54

A roothole bears S.43¼°E., 19.8 ft., with a decayed maple, size indeterminate, lying alongside, no marks visible. (Record, S.37°E.)

A decayed cedar stump, 63" dia, bears N.46°W., 21.8 ft., no marks visible.

and new bearing trees

A fir, 8" dia , bears S.46½°E., 5.2 ft., mkd. ¼ S27 BT.

A fir, 9" dia, bears N.60½°W., 12.7 ft., mkd. ¼ S28 BT.

An aluminum fence post with a U.S. Forest Service property sign is alongside the cor.