

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 10 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 394)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor. of sec. 10 only, with brass cap marked:

| 1/4
| S 10
1921

from which
An alder, 9" dia., bears N.80°E., 9 lks., mkd: 1/4 S10 BT.
An alder, 8" dia., bears S.22°E., 38 lks., mkd: 1/4 S10 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - 2/13/1974 - C.S. File 56/43-14

Found - Badly rusted iron pipe with concrete core firmly set in ground, brass cap missing.
Orig. 9" now 18" alder bears N.80°E., 5.9 ft. well healed & in good condition.
Orig. 8" alder, now 16" bears S.22°E., 25.1 ft. well healed & in good condition.

Set - Brass cap alongside remains of orig. monument mkd:
COUNTY SURVEYORS T20S R9W
OFFICE | 1/4
1974 | S 10

Fd. & used on BLM dependent resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1209, surveyed May/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18004) - FD. BC & 2 BTs

Jerry Estabrook - For: Roseburg Resources - 4/2020 - M177-2

Condition report
Found - A 1" iron pipe with brass cap (properly) marked.
ORIG. BTs -
A 23" Alder with healed face and tag bears N.80°E., 5.9'.
A 22" Alder with healed face and tag bears S.22°E., 25.1'.
BO Tied- A carsonite post bears south 3.0'
Lat. And Long. per Garmin Etrex hand held GPS:
N: 43°50'56.7" W: 123°46'05.1"