



PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

T 20 S  
S 4 | S 3  
    <sup>1/4</sup>  
R 9 W  
1975

from which the remains of the original bearing trees  
A metal capped fir stump, 53" dia., bears S.35°E., 23.1 ft., no marks visible.  
A metal capped fir stump, 61" dia., bears N.84°W., 21.8 ft., no marks visible.  
and new bearing trees  
A fir, 5" dia., bears N.80°E., 13.5 ft., mkd. 1/4 S3 BT.  
A fir, 8" dia., bears N.82°W., 18.7 ft., mkd. 1/4 S4 BT.  
The 1921-22 iron pipe, 1" dia., firmly set, projecting 4" above ground, with concrete core and brass cap missing, reset alongside the cor. by the Douglas County Surveyors Office in 1975, was found alongside.

BLM Dependent Resurvey by Jason A Lightbown, Cadastral Surveyor, Under Group No. 2841, Surveyed June/Oct. 2016 - (DCSO records Vol. 59 Page(s) 23609)

-----  
The 1/4 sec. cor. of secs. 3 and 4, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.  
from which the remains of the original bearing trees  
A metal-capped fir stump, 53" dia., bears S.35°E., 23.1 ft., no marks visible.  
A metal-capped fir stump, 61" dia., bears N.84°W., 21.8 ft., no marks visible.  
and the bearing trees mkd. by Forkner  
A fir, 10" dia., bears N.81 1/4°E., 12.5 ft., with a healed blaze. (Record, N.80°E., 13.5 ft.)  
A fir, 15" dia., bears N.79 3/4°W., 17.7 ft., with a healed blaze. (Record, N.82°W., 18.7 ft.)  
A rusted, concrete-filled iron pipe, 1" dia., firmly set, projecting 6 ins. above ground, is alongside the cor.