

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 44 Page(s) 17054-55)</p> <p>-----</p> <p>Set a Fir, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S34 on N. face, from which</p> <p>    A Fir 6" dia., bears N.4°, 6 lks. dist. mkd. ¼ S BT.</p> <p>    A Fir 7" dia., bears N.70°W., 10 lks. dist. mkd. ¼ S BT</p> <p>Old cor. bears S.88°E., 4 lks. dist. I destroy it.</p> <p>* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's &amp; Coos Bay's BLM offices.</p>
<p>GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 378)</p> <p>-----</p> <p>(Apportioned distance) Set an iron post 3 ft. long, 1" dia., 27" in the ground, for re-established ¼ sec. cor. of sec. 34 only, with brass cap mkd. <u>¼ S 34</u> 1921</p> <p>from which</p> <p>    A Fir 30" dia., bears N.24°E., 28 lks. dist. mkd. ¼ S34 BT</p> <p>    An Alder 20" dia., bears N.70°W., 16 lks. dist. mkd. ¼ S34 BT.</p>
<p>Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76</p> <p>-----</p> <p>Found - Rusted GLO 1" iron pipe (brass cap missing) with the following accessories:</p> <p>    24" D.Fir rotted staub bears N.24°E., 18.5' - no marks</p> <p>    24" Alder bears N.70°W., 10.6' - healed face</p> <p>Set - 5/8" X 30" REBAR WITH 2½" aluminum cap mkd:</p> <p>    T19S R9W</p> <p>    <u>¼ S 34</u></p> <p>    2016</p> <p>    54633LS</p> <p>Alongside iron pipe and established the following BT</p> <p>    13" D.Fir bears N.38°E., 3.7' - blazed, scribed ¼ S34 BT</p> <p>    ¼ Corner section 3 bears N.85°45'03"E., 145.52'</p> <p>    Steel post adjacent to corner.</p>
<p>1</p>