

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 320)

A Fir 36" dia., which I mark $\frac{1}{4}$ S on N. face for $\frac{1}{4}$ sec. cor., from which

A Fir 16" dia., bears S.88°W., 72 lks. dist. mkd. $\frac{1}{4}$ S BT.

A Cedar 12" dia., bears N.46°E., 70 lks. dist. mkd. $\frac{1}{4}$ S BT.

Fd. and used corner in GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Page(s) 367)

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12451-52)

The $\frac{1}{4}$ sec. cor. of 34 only, marked by the decayed shell of a Fir stump 48" dia., with partial scribe marks visible on the bark, from which the original bearing trees:

A Cedar 50" dia., bears N.51°E., 70 lks. dist., plainly blazed and healed. (Rec. bears N.46°E.)

The stump hole of an uprooted Fir 32" dia., bears S.88°W., 72 lks. dist. mkd. $\frac{1}{4}$ S on bark blaze on fallen trunk.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd: $\frac{1}{4}$ S 34
1953

from which new bearing trees:

A Fir 20" dia., bears N.49 $\frac{1}{2}$ °E., 50 lks. dist. $\frac{1}{4}$ S34 BT.

A Hemlock 16" dia., bears N.14 $\frac{1}{2}$ °W., 52 lks. dist. mkd. $\frac{1}{4}$ S34 BT.

Fd. and used in BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14219)

Douglas Co. Surveyors Office - John M. Powell, and crew - May 27, 1971 - C.S. File 53/66-18

Found - GLO brass cap, date 1953, properly marked.
20" D. Fir, now stump, N.49 $\frac{1}{2}$ °E., 33.0 ft., shows good scar.

NW. BT buried by logging show.

Set steel fence post alongside brass cap.

New BTs- 14" Hemlock S.85°W., 69.7 ft. scribed CS BT.

30" Cedar S.44 $\frac{1}{2}$ °E., 77.4 ft. scribed CS BT.

To the North of this cor. is clear cut.

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. loose, reset 12" deeper. Buried mag. marker under cap, Feb. 14, 1984 by L Roberts - M 90-53

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23078-79)

The ¼ sec cor. of sec. 34 only, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.
from which the remains of a bearing tree mkd. by the Douglas County Surveyor in 1971
A metal capped cedar stump, 36" dia., bears S.44½°E., 77.4 ft., no marks visible.
and new bearing trees
An alder, 8" dia., bears N.65½°E., 53.8 ft., mkd. ¼ S34 BT on bark.
A fir, 21" dia., bears N.32°W., 36.3 ft., mkd. ¼ S34 BT.
A steel fence post with a Property sign is alongside the cor. Corner is located N., 20 ft. and S., 30 ft. between abandoned roads, both 10 ft. wide, both bear E. and W.

Ronald L Rice - For: Oxbow Timber 1 LLC - Nov. 2015 - M170-29

Found - BLM brass cap dated 1953
36" metal capped cedar stump bears S.44½°E., 77.4',
No marks
10" alder bears N.65½°E., 53.8', Bark scribe visible
27" D.Fir bears N.32°W., 36.3' - healed face
1/4 Corner section 3 bears N.89°53'24"E., 829.24'
Steel post adjacent to corner