

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel under contract 260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 307)  
-----

Set 1/4 sec. post; 3 large rocks piled around it; from which  
A maple, 8" dia., bears N.56 1/2°E., 36 lks.  
A maple, 16" dia., bears S.52 1/2°W., 41 lks.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12496)  
-----

Point for the 1/4 sec. cor. of secs. 27 & 34, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

1/4  $\frac{S\ 27}{S\ 34}$   
1953

from which  
A maple, 16" dia., bears N.4°E., 33 lks., mkd: 1/4 S27 BT.  
A fir, 50" dia., bears S.59°W., 110 lks., mkd: 1/4 S34 BT.  
(To this tree has been nailed a wooden arrow marked RPP 838+79.70 in crayon)  
A wooden hub on preliminary center line of access road, bears S.59°W., 40 lks., wide, marked P 838+79.70 in crayon.

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO recs Vol. 37 Pg 15387)  
-----

The 1/4 Cor. Secs. 27 & 34, monumented with an iron post, 1" dia., firmly set, projecting 8" above the ground, with brass cap (properly) marked

from which the remaining BT marked in 1953  
A Fir, 52" dia., bears S.59°W., 110 lks., with fragmentary scribe marks visible on partially healed blaze.  
and a new BT  
An Alder, 6" dia., bears N.18°E., 21 lks., mkd: 1/4 S27 BT.  
Set a 6 ft. steel fence post alongside the iron post.

BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor under Group #1090, surveyed April/May 1982 - (DCSO records Vol. 45 Page(s) 17456)  
-----

The 1/4 sec. cor. of secs. 27 & 34, monumented with an iron post, 1" dia., with a brass cap, firmly set, projecting 8" above ground, w/brass cap (properly) marked

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>from which the remaining BT mkd. by Tillman &amp; Gawron A fir, 56" dia., bears S.59°W., 110 lks., with a healed blaze. and a BT by Glenn &amp; Jelley An Alder, 8" dia., bears N.18°E., 21 lks., with scribe marks S27 BT visible on a bark blaze.</p>
<p>FD. Ok by Les Roberts - 2/14/1983 - M 90-53</p>
<p>Les Roberts - Ted Baker - 3/13/1986 - C.S. File 62/30-7 ----- FD. brass cap &amp; 2 BTs - 1953 SW BT &amp; 1967 NE BT. 1953 NE BT gone. Set additional corner R.P's because of planned logging activity in near future - set hub &amp; tack R.P's with transit, see sketch (in file). Note: Corner lies on steep East slope about 50' West of Smith River Rd. Corner is also about 500' North of Scare Creek bridge.</p>
<p>Les Roberts - Ted Baker - Nov. 26 1988 - C.S. 63/50-17 ----- CONDITION REPORT Found - 1953 GLO brass cap bent over from recent logging activity. 50" fir stump, S.59°W., 76.4 ft. (scar vis.) 1953 BT. (Record, S.59°W., 72.6 ft. (NE maple BT set in 1953 is gone and 6" alder set in 1967 is down. Set - Re-set 1953 GLO brass cap firmly in ground using hub and tack R.P.'s set on 3/13/86. Buried purple magnetic marker under iron pipe. Set metal fence post, with survey attention sign wired to, beside brass cap. Corner lies on steep East slope about 50 ft. West of Smith River Road. Corner is also about 500 ft. North of Scare Creek Bridge.</p>
<p style="text-align: right;">2</p>