

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 348)

Set a post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S on N face; from which

A Maple, 12" dia., bears S.87 1/2°W., 66 lks., mkd: 1/4 S BT.

A Cedar, 10" dia., bears N.31 1/2°E., 31 lks., mkd: 1/4 S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 386)

Intersect true point for 1/4 sec. cor. determined by reference to orig. BTs, no trace of old post fd; at exact corner point Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap marked:

1/4 $\frac{S\ 10}{S\ 15}$

1921

from which (old BTs)

A cedar, 12" dia., bears N.31 1/2°E., 31 lks., mkd: 1/4 S10 BT.

A maple, 12" dia., bears S.87 1/2°W., 66 lks., mkd: 1/4 S15 BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12504)

The 1/4 sec. cor. of secs. 10 & 15, remonumented by Fred Mensch in 1921, with an iron post, 1" dia., 8" above ground, firmly set, properly marked but rusted nearly through, from which

An uprooted cedar, 12" dia., with blaze decayed, the stump hole, of which bears N.31 1/2°E., 31 lks. (OBT)

A maple, 12" dia., bears S.87°W., 66 with blaze healed. (Orig. BT)

At the corner point

In place of the rusted iron post, set a new iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

1/4 $\frac{S\ 10}{S\ 15}$

1954

from which a new BT

A fir, 50" dia., bears N.28 1/2°W., 39 lks., mkd: 1/4 S10 BT.

Deposit the old iron post alongside the new one.

Fd. Ok by Les Roberts, 2/25/1983 - M93-63

Fd. & used on BLM dependent resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1209, surveyed May/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18002)

cont.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Jason A Lightbown, Cadastral Surveyor, Under Group No. 2841, Surveyed June/Oct. 2016 - (DCSO records Vol. 59 Page(s) 23610)

The ¼ sec. cor. of secs. 10 and 15, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd.

from which an original bearing tree

A maple, 78" dia., bears S.87½°W., 43.6 ft., with a healed blaze.

and the remains of a bearing tree mkd. by Tillman and Gawron in 1953-54

A fir stump, 50" dia., bears N.28½°W., 25.7 ft., with a healed blaze.

and a new bearing tree

An alder, 13" dia., bears N.40½°E., 32.2 ft., mkd. ¼ S10 BT on bark.

Each new bearing tree has a 2½" x ¼" magnetic nail (Mag Nail) driven at the base on right side center

A rusted, concrete-filled iron pipe, 1" diam., firmly set, projecting 6" above ground, is alongside the cor.

The geographic position in NAD 1983 (2011)

Latitude: 43°50'30.36" N. Longitude: 123°45'28.93" W.