



TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

10" hemlock now 18" dia., stump 20" high with a well healed blaze bears N.69°W., 32.2 ft. (1953 dependent re-survey)  
40" fir, now a 33" dia., stump 7 ft. high with protective alum. sheeting on top & a visible scar showing bears S.33°E., 24.4' (1953 rec. S.31½°E.)  
New BT - 14" hemlock double blazed & scribed "¼ S27 CS BT" bears S.60½°W., 12.6 ft.  
Note - See L.D. Roberts PLS 1039 survey M96-20 (1984) for condition report.  
Corner is located on a newly logged flat. Reproduction is 3 or 4 years old.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23093)

-----  
The ¼ sec. cor. of secs. 26 & 27, monumented with an iron post, 1" dia. , firmly set, projecting 6" above ground, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54  
A metal capped fir stump, 38" dia , bears S.31½°E. , 24.4 ft., with a healed blaze.  
A decayed hemlock stump, 20" dia, bears N.69°W., 32.3 ft., with illegible reverse scribe marks visible on fragment of healed blaze.  
and the remains of a bearing tree mkd. by the Douglas County Surveyor in 1984  
A decayed hemlock stump, size indeterminate, bears S.60½°W., 12.6 ft., no marks visible.  
and new bearing trees  
A fir, 9" dia , bears S.36°E., 11.6 ft. , mkd. ¼ S26 BT.  
A fir, 10" dia , bears N.40°W. , 5.9 ft. , mkd. ¼ S27 BT.