

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 326)

-----

Set a post, 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which

A maple, 36" dia., bears S.26½°W., 117 lks., mkd: ¼ S BT.

A fir, 30" dia., bears N.79°E., 545 lks., mkd: ¼ S BT.

(from the corner of secs. 26, 27, 34 & 35)

S.89°42'E., on true line bet. secs. 26 & 35

37.50 chs. Compton's barn bears S., about 2.00 chs. dist.

40.17 chs. 1/4 Corner

40.92 chs. Compton's house.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12482)

-----

The ¼ sec. cor. of secs. 26 & 35 located by reference to calls of orig. field notes & the remains of an orig. BT, as follows:

- A sawed fir stump, 72" dia., bears N.79°E., 545 lks., with no marks remaining on decayed blaze; this is the only old growth tree in the immediate vicinity
- The ruins of Compton's cabin, consisting of fire place stones, broken crockery, and a few decaying cedar boards, bears East, 75 lks.
- A pile of rotting timbers, evidently the remains of Compton's barn, occupies the approx position mentioned in the field notes of the orig. survey.

At the corner point

Set an iron post, 3 long, 1" dia., 28" in the ground, with brass cap marked:

¼  $\frac{S\ 26}{S\ 35}$

1953

from which new BTs,

- A fir, 28" dia., bears N.45½°E., 9 lks., mkd: ¼ S26 BT.
- A fir, 18" dia., bears S.36°45'W., 12 lks., mkd: ¼ S35 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 37 Page(s) 15385) - Fd. BC & 2 BTs - Set a 6' steel fence post alongside the iron post.

Fd. Ok by Les Roberts - 2/27/1984 - M 96-20

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Les Roberts, LS 1039 - Nov. 14, 1987 - C.S. File 63/50-14  
-----

(Note - Corner previously referenced out Aug. 21, 1985. See C.S. 63/50-14 for reference notes.)

Found - 1953 GLO brass cap pulled out of ground by recent logging activity.

24" Fir stump, S.36°W., 8.0 ft. 1953 BT. (Rec. S.36¾°W., 7.9 ft.)

38" Fir stump, N.45°E., 6.1 ft. 1953 BT. (Rec. N.45½°E., 5.9 ft.)

Set - Re-set 1953 GLO brass cap firmly in ground using "P.K." nails set in 8/21/1985. Buried purple magnetic marker under iron pipe.

Set metal fence post, with survey attention sign wired to, beside brass cap. Painted BT stumps red

No new accessories. Corner lies on flat ground about 150 ft. North of Smith river Road.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23092)  
-----

The ¼ sec. cor. of secs. 26 & 35, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54

A fir stump, 37" dia., bears N.45½°E., 5.9 ft., with a healed blaze.

A fir stump, 23" dia., bears S.36¾°W., 7.9 ft., with a healed blaze.

and new bearing trees

A fir, 11" dia., bears N.63½°E., 11.5 ft., mkd. X BT.

A fir, 12" dia., bears S.58°W., 30.2 ft., mkd. ¼ S35 BT.

An aluminum post with property sign is alongside the cor.