

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 355)

A cedar, 10" dia., which I marked ¼ S on N side for ¼ sec. cor.; from which

A cedar, 18" dia., bears S.65°E., 9 lks., mkd: ¼ S BT.

A fir, 30" dia., bears N.44°W., 25 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12487)

The ¼ sec. cor. of secs. 14 & 23, marked by a cedar 11" dia., with scribe marks ¼S visible on partly healed blaze on N side, from which the orig. BTs:

A fir, 50" dia., bears N.44°W., 25 lks., marked BT on badly scaled bark blaze.

A cedar, 24" dia., bears S.65°E., 9 lks., plainly blazed & healed.

and a new BT

A fir, 72" dia., bears N.74°W., 20 lks., mkd: ¼ S14 BT.

John M. Phillips - For: Snellstrom Lumber Co. - Feb. 1960 - C.S. File 51/69

Note - See C.S. file 51/69 for the desc. of this corner. Data furnished by BLM since the notes are not yet recorded in the Surveyor's Office.

Upon searching for this corner in a freshly logged area:

1. I fd. the 72" fir stump & put a BLM BT tag on it. Scribe is in good shape.
2. I also fd. the 50" fir stump & put a tag on it. Scribe was not fd. however.
3. I fd. a broken off cedar stump where the 24" cedar was called for. No identification.
4. Where cedar corner was located I fd. only a root hole. I reset this ¼ corner from the two Fir BT stumps & marked the corner with a 2" pipe four ft. long sunk 40" in the ground.

(Written description of graphic in file)

From reset corner - 2"x48" IP set 40" in ground, from which

50" fir stump N.44°W., 16.50 ft.

72" fir stump N.74°W., 13.20 ft.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April/May 1967 (DCSO recs. Vol. 37 Page 15387)

The ¼ sec. cor. of secs. 14 & 23, monumented with a the remains of the orig. corner tree, a burned cedar stump, size indeterminate, no marks visible, from which the remains of the orig. BTs:

A cedar stump, 20" dia., bears S.65°E., 9 lks. no marks visible.

A fir stump, 30" dia., bars N.44°W., 25 lks., no marks visible.

and the remains of a BT marked in 1953

A fir stump, 72" dia., bears N.74°W., 25 lks., mkd. ¼ S14 BT visible on opened blaze. (Rec. 20 lks.)

and a new BT

A fir stump, 38" dia., bears S.42½°W., 30 lks., mkd: ¼ S23 BT.

A local reference monument, bears N.52°W., 7 lks., monumented with an iron pipe 2½" dia., firmly set, projecting 24" above ground.

Set a 6 ft. steel fence post alongside the iron post.

Les Roberts, PLS 1039 - For: Internation Paper Co. - Feb. 1983 - M93-63 & M93-64

Found - 2½" IP set in 1960
24" Cedar stump bears S.65°E., 5.9 ft. (no marks) 1891 BT
34" Fir stump bears N.44°W., 16.5 ft. (no marks) 1891 BT
60" Fir stump bears N.74°W., 13.2 ft. (scribe vis) 1953 BT
38" fir stump bears S.49°E., 22.7 ft. (scribe vis) 1967 BT

Set - 1½"x36" IP & brass cap beside the 2½" pipe.

New BT - 12" fir bears S.14°E., 6.4 ft. (scribed/set washer)

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22906)

The ¼ sec. cor. of secs. 14 & 23, monumented with a stainless steel post, 2½" dia., firmly set, projecting 3" above ground, with a bronze cap (properly) mkd. from which the remains of the original bearing trees

A decayed cedar stump, size indeterminate, bears S.65°E., 5.9 ft., no marks visible. continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, 34" dia., bears N.44°W., 16.5 ft., no marks visible.
and the remains of a bearing tree mkd. by Tillman and Gawron in 1953-54
A decayed fir stump, 59" dia., bears N.74°W., 13.2 ft., no marks visible.
and the remains of a BT mkd. by Glenn and Jelley in 1967
A decayed fir stump, 33" dia., bears S.49°E., 22.7 ft., with a decayed blaze.
and a bearing tree mkd. by Les Roberts, PLS No. 1039, in 1983
A fir, 32" dia., bears S.14°E., 6.4 ft., with a healed double blaze.
and a bearing tree mkd. by Forkner in 2006-09
A fir, 14" dia., bears N.39°E., 31.7 ft., with illegible scribe marks visible on partially healed blaze.
A steel fence post is alongside the cor., which falls 55 ft. N. of a spur, slopes S.50°W., and 345 ft. N. of Windy Creek Road, graveled surface, 15 ft. wide, bears N.50°E. and S.50°W.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23075-6)

The ¼ sec. cor. of secs. 14 & 23, perpetuated by Phillips, in 1960, and by Roberts, in 1983; monumented with an iron pipe, 2½" dia., firmly set, projecting 24" above ground with an iron post, 1½" dia., firmly set, projecting 6" above ground, with brass cap mkd. T2OS R9W 14 S 1/4 23 1983 PLS 1039, alongside, from which the remains of the original BTs
A decayed cedar stump, size indeterminate, bears S.65°E., 5.9 ft., no marks visible.
A decayed fir stump, 34" dia., bears N.44°W., 16.5 ft., no marks visible.
and, the remains of a BT mkd. by Tillman and Gawron in 1953-54
A decayed fir stump, 59" dia., bears N.74°W., 13.2 ft., no marks visible. (Record, 16.5 ft.)
and the remains of a BT mkd. by Glenn and Jelley in 1967
A decayed fir stump, 33" dia., bears S.49°E., 22.7 ft., with a decayed blaze. (Record, S.42½°E., 19.8 ft.)
and a BT mkd. by Roberts
A fir, 23" dia., bears S.14°E., 6.4 ft., with a healed double blaze.
At the corner point
Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, with brass cap mkd: (continued next page)

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 20 S R 9 W
S 14
¼
S 23
2009

from which

A fir, 12" dia., bears N.39°E., 31.7 ft., mkd. ¼ S14 BT. Deposit a magnet in a white plastic case at the base of the stainless steel post and dispose of the 1960 iron pipe and 1983 iron post.

From this corner, the position erroneously accepted by Tillman and Gawron, in 1953-54, for the ¼ sec. cor. of secs. 14 and 23 bears S.65°E., 5.9 ft., monumented with the decayed remains of the original SE bearing tree.