

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 361)

-----

Set a post, 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which

A fir, 36" dia., bears S.21°E., 13 lks., mkd: ¼ S BT.

A fir, 45" dia., bears N.29°E., 29 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12493)

-----

The ¼ sec. cor. of secs. 2 & 11, determined from the orig. BTs as follows:

A fir, 60" dia., bears N.29°E., 29 lks., mkd: ¼ S BT on bark blaze.

A fir, 62" dia., bears S.21°E., 13 lks., mkd: ¼ S BT on bark blaze.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

¼      $\frac{S \ 2}{S \ 11}$

1953

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23098-99)

-----

The ¼ sec. cor. of secs. 2 & 11, perpetuated by Branch, in 1987; monumented with an iron post, 1" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

A metal capped fir stump, 59" dia, bears N.29°E., 19.1 ft. to an iron rod, 5/8" dia., projecting 2" above the center of the stump with a yellow plastic cap mkd. LS 1137, with a healed blaze.

A metal capped decayed fir stump, 57" dia , bears S.21°E., 11.4 ft. to an iron rod, 5/8 in. dia., projecting 12" above the center of the stump, no marks visible. (Record, 8.6 ft.)

and new bearing trees

A fir, 12" dia, bears N.25°E., 10.6 ft., mkd. ¼ S2 BT.

A fir, 9" dia, bears S.5°W., 3.9 ft., mkd. ¼ S11 BT.

An aluminum fence post with property sign is alongside the cor.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Record of Survey for Roseburg Resources - Robert Ward -  
11/13/2025 - M186-49

-----  
Found - 1953 GLO brass cap.  
59" metal capped fir stump bears bears N.29°E.  
19.1' to a 5/8" iron rod in center of stump with  
YPC marked LS 1137 - healed face.  
57" metal capped fir stump bears S.21°E. 11.4' to a  
5/8" iron rod in center of stump - healed face.  
16" fir bears S.5°W. 3.9' - healed face.  
Aluminum post adjacent to corner.