

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T19-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 371)

The ¼ sec. cor. established on my former survey*, which is a Fir post 3 ft. long, 4" sq., 24" in the ground, mkd. ¼ S36 on N. face; from which
A Fir 25" dia., bears S.37°E., 12 lks. dist. mkd. ¼ S BT.
A Fir 6" dia., bears N.70°W., 17 lks. dist. mkd. ¼ S BT.
(* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.)

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12460)

The ¼ sec. cor. of sec. 36, T19-9, determined from the original bearing trees, as follows:
A Fir 36" dia., bears S.37°E., 12 lks., mkd. ¼ S BT on bark blaze.
A stump hole of an uprooted and rotted Fir 8" dia., bears N.70°W., 17 lks., with no marks remaining on tree.
At the corner point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼ S 36
1953
from which new bearing trees,
A Cedar 8" dia., bears N.26½°E., 11 lks. mkd. ¼ S36 BT.
A Fir 50" dia., bears N.56°W., 78 lks. mkd. ¼ S36 BT.

Ron Rice, NW Land Surveying - Jason Collver - May 2012 - C.S. File 65/76-50

Found - 2½" GLO brass cap on iron pipe, dated 1953
A Fir 36" dia., bears S.37°E., 12 lks., mkd. ¼ S BT on bark blaze. (Found 46" Fir with no marks)
A Cedar 8" dia., bears N.26½°E., 11 lks. mkd. ¼ S36 BT. (Found 24" Cedar with healed face)
A Fir 50" dia., bears N.56°W., 78 lks. mkd. ¼ S36 BT. (Found 50" Fir stump with healed. face)
New - 11" D. Fir bearing N.40°W., 22.0 ft. blazed, scribed, ¼ S36 BT
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East

Cont.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 638700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Jason A Lightbown, Cadastral Surveyor, Under Group No. 2841, Surveyed June/Oct. 2016 - (DCSO records Vol. 59 Page(s) 23602)

The ¼ sec. cor. of sec. 36 only, on the S bdy of T19S, R9W, perpetuated by Rice, in 2012; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd.

from which an original bearing tree

A fir, 48" dia., bears S.37°E., 7.9 ft., with a healed blaze.

and a bearing tree mkd. by Tillman and Gawron in 1953-54

A cedar, 25" dia., bears N.26½°E., 7.3 ft., with a double healed blaze.

and a bearing tree mkd. by Rice

A fir, 12" dia., bears N.39½°W., 21.9 ft., with a healed blaze.

The geographic position in NAD 1983 (2011)

Latitude: 43°52'13.56" N Longitude: 123°43'06.07