

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 36 only

Alias	Description

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12465)

-----  
Point for the ¼ sec. cor. of sec. 36 only, at midpoint on the E. bdy. of sec. 36.

Set an iron post 3 ft. long, 1" dia., 28" in the ground with brass cap mkd: ¼ S 36\*

1954

from which

An Alder 10" dia., bears S.46½°W., 29 lks. mkd. ¼ S36 BT.

An Alder 16" dia., bears N.39°W., 17 lks. mkd. ¼ S36 BT.

Cor. is located on a SE. slope, 42 ft. lower than the cor. of secs. 30 & 31, T20S R8W.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16710)

-----  
The ¼ sec. cor., monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap mkd. in 1954,

from which bearing trees mkd. in 1954

An Alder 14" dia., bears S.46½°W., 29 lks. dist. with fragmentary scribe marks visible on partially healed blaze.

An Alder 20" dia., bears N.43°W., 17 lks. dist., with healed blaze. (Rec. N.39°W.)

Set a 5 ft. steel fence post alongside the iron post.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22909)

-----  
The ¼ sec. cor. of sec. 36 only, on the E bdy of the Tp., monumented with an iron post, 1" dia., firmly set, projecting 14" above ground, with a bronze cap (properly) mkd.

from which new bearing trees

A fir, 10" dia., bears S.47°W., 35.3 ft., mkd. ¼ S36 BT.

A pistol-butt fir, 18" dia., bears N.80¼°W., 13.8 ft., mkd. ¼ S36 BT.

Corner falls 20 ft. NW. of an overgrown dirt road, 12 ft. wide, bears N.45°E. and S.45°W., and 85 ft. NW. of a creek, 3 ft. wide, course N.45°E.