



PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only, T20-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16714)

-----  
The true point for the 1/4 sec. cor. of sec. 18 only, determined from the remaining bearing tree marked in 1954, this point falls in a cut bank of a gravel road and is impractical to monument.

A Fir 28" dia., bears N.41 1/4°E., 31 lks. dist., with fragmentary scribe marks visible on burned blaze.  
From this point, a Witness Corner established by the County Surveyor in 1965, bears East, 66 1/2 lks. dist., monumented with an iron pipe 1" dia., firmly set, projecting 14" above ground with brass cap as marked in 1965, from which the remains of the trees mkd. by the County Surveyor in 1965

A Hemlock stump 12" dia., bears N.46°E., 7 lks. dist., with scribe marks BT visible on unhealed blaze.  
Set a 6 ft. steel fence post alongside the iron post.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21752-3)

-----  
The 1/4 sec. cor. of sec. 18 only, determined at record bearing and distance from the remains of a bearing tree mkd. by Tillman, et al., in 1953-54.

A fir stump, 26" dia., bears N.41 1/4°E., 20.5 ft., with no marks visible on partially healed blaze.  
Corner is located on edge of a graveled road, where it is impractical to establish a permanent monument.  
From this point, a witness corner established by the Douglas County Surveyor's Office in 1965, and reported by Glenn et. al., in 1967, bears East, 43.89 ft., monumented with an iron post, 1" dia., firmly set, projecting 13" above the ground, with brass cap (properly) mkd.  
from which the remains of a bearing tree mkd. by the Douglas County Surveyor's Office in 1965 and reported by Glenn, et. al., in 1967

A decayed hemlock stump, size indeterminate, bears N.46°E., 4.6 ft., no marks visible.  
and new bearing trees

A fir, 7" dia., bears N.68 1/4°E., 13.0 ft., mkd. X BT.

A fir, 9" dia., bears N.37 1/2°W., 3.8 ft., mkd. WC S18 BT.  
There is a steel fence post alongside the corner.

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22894)

-----  
The 1/4 sec. cor. of sec. 18 only, on the W. bdy. of T20S R8W determined at record dist. from the remains of a bearing tree marked by Tillman, et al., in 1953-54

A decayed fir stump, 22" dia., bears N.41 1/4°E., 20.5 ft., with the burned remains of a healed blaze.

and the remains of a bearing tree mkd. by person(s) unknown

A decayed fir stump, 27" dia., bears N.6 3/4°E., 20.4 ft., no marks visible, with a bearing tree tag mkd. S.5°W., 20 (illegible) ft., dated 1967 and 1978.

From this point the witness cor. established by the Douglas County Surveyor's Office in 1965, monumented with an iron post, 1" dia., firmly set, projecting 14" above ground, with bronze cap mkd. COUNTY SURVEYORS OFFICE WC 40' WEST TO 1/4 | S18 T20S R8W 1965, bears East, 40.00 ft. (Record, 43.89 ft.) from which the remains of a bearing tree mkd. by the Douglas County Surveyor's Office

A decayed hemlock stump, size indeterminate, bears N.46°E., 4.6 ft., no marks visible.

and bearing trees mkd. by Graham in 2005

A fir, 9" dia., bears N.68 1/4°E., 13.0 ft., with a healed double blaze.

A fir, 11" dia., bears N.37 1/2°W., 3.8 ft., with a healed blaze.

A steel fence post is alongside the witness cor., which falls on the top of the cut bank, 35 ft. N. of an overgrown graveled road, 10 ft. wide, bears N.85°E. and S.85°W.

At the corner point

Drive an aluminum rod, 36" long, 3/4" dia., 20" in the ground, with alum. cap mkd.

T 20 S  
R 9 W | R 8 W  
      | 1/4 S 18  
      2011

Corner falls on the cut bank of an overgrown gravel road, 10 ft. wide, bears N.85°E. and N.40°W. Drive an aluminum post alongside the true cor.