

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 12 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12479)

Point for the ¼ sec. cor. of sec. 12 only, at midpoint on the E. bdy. of sec. 12.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼ S 12 |
1954

from which

A Hemlock 8" dia., bears S.66°W., 33 lks. mkd. ¼ S12 BT.

A Fir 49" dia., bears N.41°45'W., 29 lks. mkd. ¼ S12 BT.

Survey by Donald Branch - For: International Paper Co. - Feb. 3, 1987 - M 101-14 and C.S. File 63/48

Found - A 1" pipe with 2" BLM cap buried 6" in the ground mkd. T20S R9W | R8W 1/4 S12 | 1954. Set witness post with attention sign.

A 16" Hemlock, down, bears S.74°W., 21 ft.± to hole with blaze and BT tag.

A 50" Fir bears N.41½°W., 19.7 ft. with signs.

New BT - 8" Hemlock bears S.5°E., 16.0 ft. scribed ¼ S7 BT. Monument is at toe of fill of road 50 ft. West.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23081)

The ¼ sec cor. of sec. 12 only, monumented with an iron post, 1" dia. , firmly set, with top 8 ins. below the surface of the ground, with brass cap (properly) mkd from which the remains of a bearing tree mkd. by Tiliman and Gawron in 1953-54

A fir snag, 51" dia., bears N.41¾°W., 19.1 ft. , no marks visible.

and a bearing tree mkd. by Donald Branch, in 1987.

A hemlock, fallen E. against a tree but still alive, 19" dia., bears S.5°E., 15.0 ft., with a healed blaze.

and new bearing trees

An alder, 6" dia., bears S.58°W., 20.9 ft., mkd. X BT on bark.

An alder, 7" dia., bears N.7½°W., 19.2 ft., mkd. ¼ S12 BT on bark.

continued next page

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 12 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2810, surveyed Sept. 2015/Jan. 2016 - (DCSO records Vol. 58 Page(s) 23452-3)

The ¼ sec. cor. of sec. 12 only, monumented with an iron post, 1" dia., firmly set, with top flush with the surface of the ground, with a brass cap (properly) mkd. from which the remains of a bearing tree mkd. by Tillman and Gawron in 1953-54

A fir snag, 52" dia., bears N.41¾°W., 19.1 ft., with no marks visible and a nail at the base on the left side center.

and a bearing tree mkd. by Branch, PLS No. 1137, in 1987

A leaning hemlock, 21" dia., bears S.5°E., 15.0 ft., with a healed blaze and a nail at the base on the right side center.

and the bearing trees mkd. by Forkner in 2006-09

An alder, 11" dia., bears S.56½°W., 20.9 ft., with axe marks X at breast height, scribe marks BT visible on bark at base, and a Mag Nail at the base on the right side center. (Record, S.58°W.)

A willow, 10" dia., bears N.7½°W., 19.2 ft., with scribe marks ¼ S12 BT visible on bark and a Mag Nail at the base on the right side center. (Record, alder.)

An aluminum fence post with a Forest Service sign is alongside the cor.

From the corner

North, 25 ft., centerline of graveled road, 10 ft. wide, bears N.55°E. and S.40°W.