

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John W. Meldrum, under contract No. 116 dated Dec. 12, 1867 - (DCSO records Vol. 1 Page(s) 180)

-----  
Fir tree, 60" dia., marked for ¼ sec. corner.  
A Hemlock, 15" dia., bears N.40°W., 10 lks.  
A Hemlock, 18" dia., bears S.30°E., 9 lks.

Roy Gibson - June 1957 - C.S. File 42/275

-----  
1/4 Corner 29/30  
Orig. 60" Fir snag at corner from which  
32" Hemlock bears N.43°E., 32' (knife scribed 25 years old, not orig.)

Douglas Co. Surveyors Office - Gary Commons - Pete Earle - Jan. 16, 1975 - C.S. File 57/17-7

-----  
Found - 60" D.Fir snag, is now a stump, extremely rotted on outside.  
32" Hemlock N.42°E., 34 ft. (rec. N.43°E.,, 32.0 ft) is now a 34" stump. We opened scribe & found "CS" on portion of tree removed by fallers. We opened & found "BT" (we attached this to top of stump). The first record I could find of this BT was in the field notes of railroad creek survey by Roy C. Gibson for E. K. Wood Lbr. in 1957. He found BT & stated it was not orig. Knife scribed 25 years old.  
Set - A railroad spike with "X" marked on head in center of 60" D.Fir.  
A 6" Hemlock, bears N.56°E., 40.6 ft. scribed "¼ S30 CS BT"  
A 12" Hemlock, bears N.57°W., 81.6 ft scribed "¼ S30 CS BT"

Daniel Baker, LS 1978 - For: USFS - June 10, 1986 - M 102-12

-----  
Found - Boat spike with "X" in top in center of rotted fir stump.  
14" rotted Hemlock stump, N.6°E., 9.5 ft. (no rec.)  
30" rotted Hemlock stump, N.40½°E., 34.1 ft.  
20" Hemlock N.56°E., 40.6 ft. (scribe visible)  
36" Fir stump, S.52°E., 26.4' (USFS tag - not of rec)  
Set - I referenced the boat spike, then pulled it & replaced it w/a 5/8"x27" rebar with 3" alum. cap mkd: T20S R10W ¼ S30 S29 PLS 1978 1986"

continued next page

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Jerry Estabrook - For: Menasha Log Co. LLC The Campbell Group, LLC ITS Manager - 3/2012 - M163-41

-----

Found - 5/8" iron rod with 3" aluminum cap marked "T20S R10W  
¼ S29 S30 PLS 1978 1986" in 60" fir stump with  
two iron fence post and signs alongside.  
A rotten hemlock stump with no visible marks brs.  
N.06°E., 9.5'.  
A 30" hemlock stump with tags brs. N.40°E., 34.1'.  
A 34" hemlock with healed face and tag brs. N.56°E.,  
40.6'.  
A 36" fir stump with tag brs. S.52°E., 26.4'  
A 36" hemlock with healed face and tags brs.  
N.57°W., 81.6'.

Fd. alum. cap & 4 BTs. Jerry Estabrook - June 2014 - M168-20  
Lat. and Long. per Garmen Etrex hand held GPS:  
N: 43°48'13.8" W: 123°55'36.3"