

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 239-240)

Set post, 4 ft. long, 3½" sq., 24" in the ground for ¼ sec. cor., mkd: ¼ S on W face; from which
 Fir, 8" dia., bears S.2½°W., 46 lks., mkd: ¼ S BT.
 Fir, 9" dia., bears S.69½°E., 58 lks., mkd: ¼ S BT.

Jerry Estabrook - For: Menasha Log Co. LLC & The Campbell Group LLC ITS Manager - May 2012 - M163-55 & C.S. 65/75-5

REPORTED AS NOT FOUND
I searched for the original West ¼ corner, but could not find it. Richard Hintz calculated this corner at a midpoint between the section corners when he subdivided Section 17 as shown on M90-42. However, the GLO notes call for the ¼ corner to be 40.45 chains from the section corner to the north and 40.00 chains from the section corner to the south. The GLO notes also say that the ¼ corner falls on a ridge. For these considerations a lot of thought and reasoning is going to be needed to establish the ¼ corner in question.