

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T19-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 214)</p> <p>-----</p> <p>Set post, 4 ft. long, 3½" sq., 24" in ground for ¼ sec. corner mkd. ¼ S on N. face; from which a Maple 5" dia., bears N.15°E., 15 lks. dist. mkd. ¼ S BT Chittem 4" dia., bears S.20°W., 150 lks. dist. mkd. ¼ S BT.</p>
<p>GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 262)</p> <p>-----</p> <p>"No corners are found between the cor. of secs. 4, 5, 32 and 33, and the cor. which I accept as cor. of Tps. 19 and 20 S., R. 10 W., but I find a fairly continuous line of old blazes extending as far as this Tp. cor., but no further eastward."</p>
<p>BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11682-83)</p> <p>-----</p> <p>Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼ $\frac{S\ 33}{S\ 4}$ 1952</p> <p>from which A Fir 55" dia., bears N.75°E., 144 lks. dist. mkd. ¼ S33 BT. A Fir 48" dia., bears S.8°W., 11 lks. dist. mkd. ¼ S4 BT.</p>
<p>Corner report by Ernesto R. Alvarado, U.S.F.S., Deputized by DCSO - Wit: Diane Lawson - Nov. 8, 1978 - C.S. File 60/17-23</p> <p>-----</p> <p>Found - 1952 GLO brass cap properly mkd. 40" D.Fir bears S.6°W., 7.1 ft. 43" D.Fir bears N.75°E., 97 ft.</p> <p>CONDITION REPORT ONLY. NO NEW MONUMENT OR ACCESSORIES. Go to sec. cor. for 32, 33, 4 and 5 which is located 6 ft. East of N.Fork Access Road. From there, go East 1/2 mile to corner.</p>
<p>Fd. OK, Sept. 1980 by D. Peel - M 85-46 Fd. OK, Dec. 1990 - M 111-33</p>
<p style="text-align: right;">1</p>