

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 only, (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 160)

-----  
Intersect West bdy. of tp. (T20-11) 305 lks. S. of cor. to secs. 7, 18, 12 & 13.

At point of intersection

I set a post for closing cor. to secs. 18 and 7, 4 ft. long, 4" sq., 24" in the ground, marked S7 on N.; CC T20S R11W on E.; S18 on S. faces, with 2 notches on N. and 4 notches on S. faces; from which

A Spruce 6" dia., bears N.87°E., 165 lks. dist. mkd. T20S R11W S7 BT.

A Vine Maple 4" dia., bears S.43°E., 36 lks. dist. mkd. T20S R11W S18 BT.

An Alder 6" dia., bears S.26°W., 37 lks. dist. mkd. T20S R11W CC S7 & 18 BT.

June 17, 1892

-----  
Corner report by W.J. Brayton, having been set by #2157 - May 1954 - C.S. File 41/194

4" post set by #2157. 1½" Iron pipe, from which

7" Spruce S.60°W., 10.2 ft.

48" Fir N.54°E., 108.0 ft.

6" Spruce S.80°E., 38.0 ft.

-----  
Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron - March 1970 - C.S. File 53/66-98

Found - 1½" Iron pipe and BTs as called for by Brayton  
48" now 54" Fir, alive, N.54°E., 108.0 ft., shows good scar, we tag.

7" now 9" Spruce, dead, decaying, S.60°W., 10.2 ft., scribe visible.

Orig. 18" Alder snag, N.69°E., 23.3 ft. scribe visible by #399.

SE bearing tree gone.

New BTs -22" Spruce N.43°E., 31.4 ft. mkd. T20S R11W S7 CC CS BT.

20" Spruce S.63°E., 62.5 ft. mkd. T20S R11W S18 CC CS BT.

This closing cor. lies on E. edge of clear cut which extends North to corner of secs. 12 and 13.

-----  
Survey by Daniel Baker - For: International Paper Co. and Davidson Industries - July 1988 - M 106-67

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 (West)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Found - 2" very rusted pipe.  
35" Spruce N.45°E., 30.5 ft.  
54" Fir stump N.52°E., 108.0 ft.  
32" dead Spruce S.61½°E., 62.0 ft.  
Set 3/4" x 42" alum. rod and cap mkd. "RLS 1978 S13|S7 S18  
R12W R11W 1988".

Fd. OK by T. Hostetter, Sept. 1999 - M133-40  
Note - There is also a 22" Alder W/BT tag approx. 5 ft. SW of  
the cap.

Robert B. Ward - For: Roseburg Resources - 5/25/2010 - C.S.  
File 65/69-19

-----  
This corner was referenced and then removed to allow for the  
construction of a logging spur. I re-set the removed corner  
back to its orig. position based on reference point. The  
corner now falls just east of the easterly shoulder of a  
newly constructed logging road spur.

Found - Alum. cap, properly marked, ¾"x42" alum. rod.  
36" spruce stump, healed face, N.40°E., 30.50'  
New BT - 18" twin fir, scribed "T20S R12W S13 BT" N.46°W.,  
80.00'  
New BOs- 47" Hemlock stump, 60D nail in center of stump,  
S.83°E., 134.00'  
28" Hemlock stump, 60D nail in center of stump,  
S.60°E., 164.90'