

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 155-156)

-----  
Set a post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on N. face; from which  
A Maple 10" dia., bears N.13°E., 15 lks. dist. mkd. 1/4 S BT  
A Fir 40" dia., bears S.1°W., 14 lks. dist. mkd. 1/4 S BT.

Survey by Warren D. Hootman - For: Crown Zellerbach Corp. - Jan. 30, 1963 - M 22-36 and C.S. File 51/247-1

-----  
1" Iron pipe, from which  
14" Spruce N.13 1/2°E., 32.80 ft.  
24" Spruce stump, N.88°W., 44.15 ft.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Feb. 1970 - C.S. File 53/66-7

-----  
Found - 3/4" alum. pipe, loosely set.  
Did not find any orig. BTs.  
24" Spruce stump, poor condition, S.17°W., 15.5 ft. scribe barely visible.  
30" Spruce stump, poor condition, N.59°W., 19.8 ft. scribe barely visible.

Set Brass cap at cor. mkd: County Surveyors Office  
T 20 S R 11 W  
1/4 S 18  
S 19  
1970

Reset old pipe alongside.

New Accessories:

4" D.Fir S.54°E., 56.3 ft. mkd. 1/4 S19 CS BT.  
4" Spruce N.20°W., 58.5 ft. mkd. 1/4 S18 CS BT.  
5/8" Iron rod West, 10.0 ft.  
5/8" Iron rod North, 15.0 ft.

This corner lies about 50 ft. West and 50 ft. South of top of spur sloping NW.

Fd. OK, Feb. 1993 by John Minor - M 116-56

Fd. OK, June 1996 by John Minor - M 125-26