

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 117)

Set a post 4½ ft. long, 4" sq., 24" in the ground, for cor. to secs. 5, 6, 31 and 32, marked T20S S32 on NE.; R11W S5 on SE.; T21S S6 on SW.; S31 on NW. faces, with 1 notch on W. and 5 notches on E. edges; from which

- A Fir 27" dia., bears N.56½°E., 26 lks. dist. mkd. T20S R11W S32 BT.
 - A Fir 36" dia., bears S.29½°E., 35 lks. dist. mkd. T21S R11W S5 BT.
 - A Fir 42" dia., bears S.22°W., 20 lks. dist. mkd. T21S R11W S6 BT.
 - An Alder 6" dia., bears N.12½°W., 8 lks. dist. mkd. T20S R11W S31 BT.
- Aug. 17, 1891

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - P. Earle; K. Cheney, crew - March 2, 1977 - C.S. File 59/31-1

Found - Orig. 42" Fir now a 46" decayed stump. Has well healed blaze, which we open. Find good scribing "T21S R11W S6 BT"

Orig. 27" Fir now a 34" tipout (root hole well defined). Tree has well healed blaze which we open, find good scribing "T20S R11W S32 BT". Tree is decayed.

Possible orig. BT to the SE recorded as a 36" Fir, fd a badly decayed stump, no scribing, approx 18" NW BT, an Alder, not found.

Set a 1" x 36" I.P. with brass cap attached 30" deep at sec. cor. mkd: Douglas County Surveyor T20S R11W S31 S32 S6 S5 T21S 1977, from which

46" Fir stump bears S.22°W., 13.2 ft. to face.
Stump hole bears S.27°E., 23.1 ft. to center (Rec. S.29½°E., 23.1 ft.)

New BTs -A D.Fir 14" bears S.39°W., 16.5 ft. Tree double blazed and scribed "T21S R11W S6 CS BT"

A D.Fir 14" bears S.62½°E., 4.6 ft. Tree double blazed and scribed "T21S R11W S5 CS BT"

A W.Fir 9" bears N.34½°W., 14.2 ft. Tree double blazed and scribed "T20S R11W S31 CS BT"

A D.Fir 18" bears N.7°E., 25.2 ft. Tree double blazed and scribed "T20S R11W S32 CS BT"

This corner falls on the top of a ridge running S.35°W.

FD. 1977 BC & accessories by T. Hostetter, 4/2008 - M155-72