

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 165)

-----  
Set a post 5 ft. long, 5" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on W. face; from which  
A Fir 10" dia., bears N.85°W., 100 lks. dist. mkd. ¼ S BT  
A Fir 12" dia., bears East, 9 lks. dist. mkd. ¼ S BT.

Survey by G. H. Waggoner, Deputy Co. Surveyor, Lane County - Wit: C. Johnson and Wm. Gibson - April 16, 1934 - C.S. File 53/1-77

-----  
Found - I find the BT described as a 12" Fir bearing East 9 lks., showing original marks.  
Set Cedar post 4 x 4" mkd. C S and mkd. new BTs as follows:  
18" Fir mkd. CS BT bears N.33°W., 12.9 ft.  
16" Fir mkd. CS BT bears S.12½°E., 16.3 ft.  
18" Fir which seems to have been marked as a BT, bears N.75°W., 8.6 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron - Feb. 25, 1970 - C.S. File 53/66-93

-----  
Found - Unrecorded 1¼" steel shaft set for cor. with 4"x4" white painted cedar post and BTs as follows:  
Orig. 12" now 28" Fir, badly decayed, East 5.9 ft., scribe marks visible.  
18" now 24" Fir, 20 ft. high snag, N.33°W., 12.9 ft., shows scar.  
16" now 26" Fir stump, S.12½°E., 16.3 ft., shows scar.  
A stump, N.75°W., 8.6 ft., but is not a BT.  
We Do Not Set Brass Cap.  
New BTs- 9" Alder N.45°W., 16.0 ft. mkd. "¼ S6 CS BT" on bark  
8" Alder S.26°W., 13.9 ft. mkd. "¼ S6 CS BT" in wood  
7" Alder S.70°E., 11.1 ft. mkd. "¼ S5 CS BT" in wood  
5" Alder N.34°E., 14.5 ft. mkd. "¼ S5 CS BT" on bark

Fd. OK, Dec. 23, 1987 by D. Baker - M 105-40  
Fd. Ok by Harvey Christensen, 8/2002 (filed 1/27/2006) - M149-39