

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 144)

Set a post, 3 ft. long, 3' sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on W. face; from which

A Fir 8" dia., bears S.74°W., 7 lks. dist. mkd. 1/4 S BT.

A Fir 6" dia., bears S.42°E., 11 lks. dist. mkd. 1/4 S BT.

Survey by Tom McCullough - For: U.S. Forest Service (Siuslaw National Forest) - Feb. 1970 - C.S. File 55/142-5

Found - 1" Pipe, (See M 20-44), from which

26" Fir stump bears S.74°W., 4.6 ft. (orig.) face chopped out, scribing visible.

Set 2" x 30" Iron pipe with brass cap mkd. T20S R11W

8|9 1/4

1970

650

from which

18" Fir stump bears N.50°E., 35.0 ft. scribed 1/4 BT, with tag.

Set 2 fence posts with signs ± 5.0 ft. West facing South and ± 5.0 ft. South facing West. (See also DCSO 2/1970 report C.S. 53/66-111 - visit was after corner set but before filed)

Kris DeGroot - For Siuslaw National Forest - 10/2008 - M157-6

Found - 2" iron post by McCullough in 1970, firmly set, projecting 6" above the ground, with 2" brass cap (properly) stamped, from which

Orig. BT by Thiel in 1891: A 26" rotted fir stump, bears S.72°45'W., 4.9 ft to the face, with scribes marks "8 BT" visible on open face (Rec. S.74°W., 4.6 ft.)

McCullough 1970 BT: The rotted remains of a 18" fir stump bears N.51°15'E., 34.9 ft., no blaze visible. (Rec. N.50°E., 35.0 ft.)

New - 17" D.Fir bears S.30°15'W. 26.6 ft scribed "1/4 S8 BT"

14" D.Fir bears N.60°45'E. 20.1 ft scribed "1/4 S9 BT"

1" iron pipe per M24-52, is set alongside, & projects above the top of the BCIP.

Jonathan B. Drew, II, USFS - Assisted by: Andrew Hillman - 11/10/2015 - C.S. File 65/90-75

Found - A 2 1/2" brass cap on 2 1/4" galvanized iron pipe, projecting 3" above the ground.

continued next page

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 26" fir stump with scribe visible on a prev. opened single blaze. (S.74°W., 4.6 ft) 1891 1961 1970 1975 1982
No trace found of a (6" fir) 1891 (Fir stump)1961 (S.42°E., 7.3 ft) 1891 & 1961
A 14" fir stump with no marks visible. (N.50°E., 35.0 ft) 1970, 1975 & 1982
A 17" fir with a healed double blaze. (S.30°15'W., 26.6 ft) 2008
A 15" fir with a healed double blaze. (N.60°45'E., 20.1 ft) 2008
A 1¼" iron pipe bears S.40°E., 0.60 ft. projecting 6" above ground. (Alongside) 2008
No new accessories added.
No new measurements to BTs. Filed as condition report. Bearing to fd iron rod by hand compass, distance by steel tape.
Corner maintenance/other info -
Clear brush from around monument and to BTs. Tie flagging to monument and guard posts. Paint BT Faces & a 6" band at head height, add new nails to existing BT tags & add new tags where needed.
Geodetic coordinates -
Lat N 43°50'49.768" Long W 124°01'35.241"
Datum - WGS 84
Source - Cell phone GPS for navigation to corner