

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 144)

Set a post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 4, 5, 8 and 9, mkd. T20S S4 on NE.; R11W S9 on SE.; S8 on SW.; S5 on NW. faces, with 5 notches on S. and 4 notches on E. edges; from which

A Cedar 10" dia., bears N.87°E., 127 lks. dist. mkd. T20S R11W S4 BT.

A Vine Maple 4" dia., bears S.17°E., 50 lks. dist. mkd. T20S R11W S9 BT.

A Fir 15" dia., bears S.73°W., 3 lks. dist. mkd. T20S R11W S8 BT.

A Cedar 36" dia., bears N.27°W., 100 lks. dist. mkd. T20S R11W S5 BT.

June 1, 1892

Survey by Warren D. Hootman - For: Cape Arago Lumber Co. - Sept. 10, 1957 - C.S. File 42/305

Found - The remains of the original corner post.
The orig. Cedar BT in Sec. 5, which is blown down and the scribing is almost gone.

I set a 4" x 4 ft. Cedar post next to the original corner post, and scribe four new BTs:

Western R. Cedar 14" DBH, bears S.32°00'E., 42.5 ft.

Alder 21" DBH, S.60°30'W., 31.5 ft.

Alder 16" DBH, bears N.80°00'W., 39.0 ft.

D.Fir 22" DBH, bears N.6°00'E., 74.5 ft.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, V. Perron, crew - Feb. 24, 1970 - C.S. File 53/66-92

Found - Cedar post, in place.
22" now 24" D.Fir, alive, N.4°E., (Rec. N.6°E) 74.5 ft., scribe visible on nearly healed blaze.

21" now 23" Alder, alive, S.60½°W., 31.5 ft., scribe visible on healing blaze.

14" now 17" Cedar, alive, S.28°E., (Rec. S.32°E.) 42.5 ft., nearly healed blaze.

NW. Alder BT gone.

Orig. 36" Cedar BT to NW. still in evidence.

Set Brass cap at cor. mkd: County Surveyors Office

T 20 S R 11 W

S 5 | S 4

S 8 | S 9

1970

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Reset Cedar post alongside.
No suitable trees to NW. for BT.
Corner lies on steep NE. slope 66 ft. North of top of spur
sloping East and 40 ft. South of canyon, course East.

April 1970, Set fence post with sign ± 5 ft. West, facing
North - C.S. File 55/148-9

Survey by Gerald K. Attig, LS #1121 - For: U.S. Forest
Service - Nov. 1981 through Jan. 1982 - M 91-20

Found - DCSO brass cap, properly marked.
24" Fir bears N.4°E., 74.5 ft. with healed face.
24" Alder bears S.63°W., 31.5 ft. with scribe
visible.
20" Cedar stump bears S.32°E., 42.5 ft. with healed
face.
New BTs - 32" Fir mkd. "T20S R11W SE S5 BT" bears N.13°W.,
86.8 ft.
20" Fir mkd. "T20S R11W SW S4 BT" bears N.46½°E.,
52.0 ft.