

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T21-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 8)

Set post corner of secs. 4, 5, 32 and 33, from which
An Alder 15" dia., bears S.11°W., 16 lks. dist.
An Alder 18" dia., bears N.80°W., 25 lks. dist.
A Hemlock 8" dia., bears N.63°E., 75 lks. dist.
A Spruce 80" dia., bears S.21°E., 50 lks. dist.

Survey by W.G. Corbitt; H. Hendrickson - For: Crown Zellerbach Corp. - July/Aug. 1943 - C.S. File 52/91

Found - Orig. 8" Hemlock, really only 5" when scribed, now 12" scribed "T12W (?) R20S S33, from it, relocated cor. S.63°W., 49.5 ft. Creek W., 75.5'

Crayon mkd:

- 5 ft. Spruce stump S.28°E., 27.1 ft. "RP BT S4 out 27.1 ft."
- 6 ft. Spruce stump "RP BT S5 out 106.7 ft." S83°W., 106.5 ft.
- 6 ft. Spruce stump "RP BT S32 out 98.1 ft." N.70°15'W., 98.2 ft.
- 3 ft. Hemlock stump "RP BT S33 out 41.4 ft." N.83°E., 41.4 ft.
- N.86°30'E., 72.2 ft. to face of old blaze 86 yrs. old on 3 ft. Spruce stump. West side of truck road.

Set 1½" I.P., 2x2x5 Fir post, crayon mkd. "S32 S33 T20S R12W S5 S4 T21S R12W" with diamond shape betw. sec. numbers.

Fd. and used in Ore. State Hwy Dept. survey, 1952, filed with DCSO as D-3

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17192)

The cor. of secs. 4, 5, 32 and 33, perpetuated and recorded by Corbitt in 1943, monumented with an I.P. 1½" dia., firmly set, projecting 4" above ground, from which the remains of the original bearing tree:

A decayed Hemlock stump 12" dia., bears N.63°E., 75 lks. dist., no marks visible.

At the corner point

Set an alum. post, 28" long, 2 1/2" dia., 20" in the ground, directly over iron pipe, with alum. cap mkd:

(Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T21-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>T 20 S R 12 W <u>S 32 S 33</u> S 5 S 4 T 21 S 1981</p> <p>from which new bearing trees: An Alder 5" dia., bears N.35°E., 47 lks. dist. mkd. T20S R12W S33 BT. A Spruce 11" dia., bears S.61¼°E., 51 lks. dist. mkd. T21S R12W S4 BT. A Spruce 13" dia., bears S.70°W., 127 lks. dist. mkd. T21S R12W S5 BT. A Spruce 10" dia., bears N.68¼°W., 135 lks. dist. mkd. T20S R12W S32 BT.</p>
<p>Fd. OK, in BLM resurvey by Goodson, Tawney and Acuna, under Group #1077, surveyed Sept. 1981/Oct. 1982 - (DCSO Records, Vol. 44 Pages 17112-13</p>
<p>Fd. OK, April 1995 by Robert Ward - M 122-3 A Fd. Ok, March 1997 by Christine Blevins, ODOT, M 129-38</p>