

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 31)

An Alder 12" dia., is gr. sec. corner, from which
An Alder 24" dia., bears S.83°E., 25 lks. dist.
An Alder 15" dia., bears West 40 lks. dist.

Survey by W.G. Corbitt; H. Hendrickson - For: Crown Zellerbach - July 29, 1943 - C.S. File 52/91

Set 1½" I.P. and 2x2x5 ft. Spruce post at point 2654.5 ft. from cor. of 4, 5, 32 and 33, from which bears:
24" Hemlock S.48½°W., 8.5 ft. "RP 26+54.5".
5" Spruce N.11°E., 75.2 ft. "RP 26+54.5 ft."
Other post for approx. ¼S, N.20½°E., 88.5 ft.
Edge of logging 107-31=102.2 East from 27+37.2 to pipe and post mkd. ¼ S32 33 1243' E. of 1/16 cor.
Original corner or BTs not found. Did find blazes on 8" Spruce made in 1922.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17113)

The ¼ sec.cor. of secs. 32 and 33, reestablished at proportionate distance and recorded by Corbitt in 1943, and is accepted as the best available evidence of the position of the original corner, monumented with an iron pipe, 2" dia., firmly set flush with the ground, from which the remains of bearing trees mkd. by Corbitt:

A rotted Spruce stump 5 ft. dia., bears N.11°E., 114 lks. dist., no marks remaining.

A rotted Hemlock stump, size indeterminate, bears S.48½°W., 13 lks. dist., no marks remaining.

At the corner point

Set an alum. post 28" long, 2½" dia., 25" in the ground, with alum. cap mkd:

T 20 S R 12 W
1/4
S 32 S 33
1981

from which new bearing trees

A Spruce 32" dia., bears N.44 3/4°E., 33 lks. dist. mkd. ¼ S33 BT.

A Spruce 15" dia., bears S.26°W., 22 lks. dist. "¼ S32 BT.

Deposit the iron pipe alongside the aluminum post.

Fd. OK, April 1995 by R. Ward - M 122-3 A

