

PRIMARY CORNER DESCRIPTION M.C. W. bdy. Sec. 15

Alias 961814 Description M.C. bdy. Lake Tahkenitch  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 29)

-----  
Set post, from which

A Spruce 24" dia., bears N.5°E., 12 lks. dist.

A Spruce 12" dia., bears N.27°W., 20 lks. dist.

-----  
Survey by W.G. Corbitt; J.K. Elliott - For: Crown Zellerbach - May 1, 1943 - C.S. File 52/91

-----  
Found 12" Spruce BT stump standing. The 25" Spruce was dead and down. Dug into rotten trunk and found old blazed face with scribe marks S15. Had to reset corner from 12" stump. Set 1½" I.P. and 4x4x5 ft. post, crayon mkd. "S16 S15 M.C. 1943", from which bears:

Orig. 12" Spruce stump now 14", N.27°W., 13.2 ft. nail scribed "BT". Rest covered.

40" Spruce stump, N.4°30'E., 9.3 ft. to nail, crayon mkd "MC RP BT"

Corner stands 2 ft. above water at this date, in thicket of huckleberry.

-----  
Robert Ward, L.S. #1091 - For: Siuslaw National Forest & Tahkenitch Tree Farm Partnership - April 1995 - M 122-3B

-----  
Found - 2" Rusted pipe set by Corbitt.

12" Rotted Spruce stump, bears N.27°W. 13.2' to face vis. scribing.

40" Rotted Spruce stump, bars N.5°E., 9.0' to face, no scribing.

Set 8'x3/4" aluminum rod with 3" Alum. cap into center of 2" rusted pipe, cap mkd:

T20S R12W

S16 S15

MC

1994

LS 1091

BTs - 12" Spruce, bears N.35¼°W., 31.7', scribed: "T20S R12W S16 MC BT".

24" Hemlock, bears N.51½°E., 56.4', scribed: "T20S R12W S15 MC BT".

Both BTs have brass washer stamped "LS 896" nailed to center of lower face on New BTs.