

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 20)

Set ¼ sec. post, from which
A Spruce 36" dia., bears S.16°E., 12 lks. dist.
A Spruce 15" dia., bears N.34°W., 23 lks. dist.

Survey by W.G. Corbitt; B. Senn - For: Crown Zellerbach - Oct. 30, 1941 - C.S. File 52/91

Found stumps of the orig. BTs at ¼ cor. showing scribe marks. As bearings and distances would not check exactly, I relocated corner as near as possible.
Set 1½" I.P. and 2"x4"x5 ft. Fir post, from which bears,
Orig. 36" Spruce stump S.16°E., 8.5 ft. to nail scribed 1/. Rest burnt off.
Orig. 15" Spruce stump N.30°W., 15.7 ft. scribed BT. Stump rotten and burnt.
I blazed:
24" Spruce stump N.27°W., 27.4 ft. to nail, crayon mkd. "¼ S10 BT".
Corner stands on SW slope of ridge about 4.0 ft. E. of N. and S. truck road to Harmony Bay. The phone line to Booth passes close to corner.

Survey by Richard J. Hintz - For: G. Karjiloff - Oct. 1966 - M 32-31

Found - 2" I.P.
Orig. Spruce stump, bears S.16°E., 7.9 ft.
New BTs -12" Hemlock bears S.81½°E., 15.2 ft. "¼ S11 BT" (metal tag)
12" Fir bears S.51½°W., 18.6 ft. "¼ S10 BT".

Stuntzner Engineering & Forestry - For: Western Pacific Timber Survey - November 15, 1992 - M 116-32

Found - 1½" inside dia. iron pipe.
46" rotten Orig. Spruce stump with visible scribe bears S.16°E. 10 ft.
22" Hemlock with healed face & tag bears S.81°30'E. 15.35 ft.
12" Fir with healed face & tag bears S. 51°30'W. 18.4 ft.
Set ¾" x 30" iron rod (set inside iron pipe) with 2" alum. cap marked: ¼ S10 S11 1992 LS 1342.