

PRIMARY CORNER DESCRIPTION M.C. on E. bdy. Sec. 10

Alias <u>956610</u>	Description <u>M.C. bdy. Siltcoos Lake</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 21)

(71.02 chs.)

Set post, from which

A Spruce 12" dia., bears N.78°E., 22 lks. dist.

A Fir 36" dia., bears N.21°W., 40 lks. dist.

Survey by W.G. Corbitt; B. Senn - For: Crown Zellerbach - April 14, 1943 - C.S. File 52/91

Found orig. 36" Fir stump BT for M.C. at 71.02 chs. and from it relocated the M.C. as the Spruce tree is missing.

Set 1½" I.P. and 3"x3"x4 ft. post, from which bears:

36" orig. Fir stump N.21°W., 26.4 ft. to nail in bark between scribe marks S R 12 W and 26.8 ft. to nail in wood above old springboard hole.

18" Hemlock across Harmony Bay bears S.15°30'E.

Found a 6"x6"x3 ft. post scribed C.S. M.C. on the bank near the Fir BT. Evidently removed from correct position and laid there to protect it from high water as the I.P. now stands 2 ft. above water level.

Survey by Karl Foeste - For: Crown Zellerbach; Sparrow Pacific Corp. and U.S. Forest Service - Nov. 25, 1974 - C.S. File 58/25 and M 56-1

I found the orig. 36" Fir BT set by Gordon in 1858. It is now a stump with nail above spring board hole as reported by Corbitt in 1943. Scribing is no longer visible and I could not find Corbitt's 1½" I.P. I measured from said nail, S.21°E., 26.8 ft. and set flush, a 2" x 36" concrete filled galv. I.P. with 3" brass cap fully stamped. The NE BT is missing.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17106)

The middle meander cor. of secs. 10 and 11, on Siltcoos Lake, perpetuated and recorded by Foeste in 1974, bears S.2°28'E., 8.99 chs. dist. (from Sec. cor. 2, 3, 10 and 11), monumented with an I.P. 2½" dia., firmly set, projecting 4" above ground with brass cap mkd: LS 849 T20S R12W S10 S11 MC 1974, from which the remains of an original bearing tree

A sawed Fir stump 38" dia., bears N.20½°W., 42½ lks. dist. (40 lks. to face), no marks visible on open rotted blaze. (Rec. N.24°W., 40 lks.) (Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 500571

PRIMARY CORNER DESCRIPTION M.C. E. bdy. Sec. 10

Alias 956610 Description M.C. bdy. Lake Siltcoos

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

and a new bearing tree

A Spruce 15" dia., bears N.64°W., 79 lks. dist. mkd. T20S  
R12W S10 MC BT.

No suitable tree available in sec. 11.