

PRIMARY CORNER DESCRIPTION Sec. cor. for 35 & 36; 1 & 2 of T21-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 5 & 6)

Set post corner of secs. 1, 2, 35 and 36, from which
An Alder 18" dia., bears S.12°E., 27 lks. dist.
An Alder 30" dia., bears S.83°W., 39 lks. dist.
An Alder 12" dia., bears N.28°W., 50 lks. dist.
An Alder 20" dia., bears N.41°E., 40 lks. dist.

Survey by Richard J. Hintz - For: Champion International and International Paper - March 1980 - C.S. File 58/140 and M 79-30

Found broken 1 3/4" I.P. lying on the ground, (unrecorded), from which,

A 48" Fir stump bears N.78°E., 1.0 ft.
Set stamped 2" I.P. with brass cap, from which
14" Fir bears N.21°30'E., 35.0 ft., scribed.
48" Fir stump bears N.78°00'E., 1.0 ft.
22" Fir bears S.51°15'E., 40.3 ft., scribed.
12" Hemlock bears S.13°00'W., 40.2 ft., scribed.
10" Spruce bears N.50°30'W., 53.8 ft., scribed.

This corner was tied in by a Bonneville Power Admin. crew on Dec. 2, 1948, at which time the I.P. was in place. The Fir was a green tree, but was erroneously called a Spruce by the crew. A copy of their field notes, Index No. A49-386A, may be obtained by contacting John Sink, Dept. of Energy, P.O. Box 3621, Portland, Oregon 97208.

Survey by Ronald Stuntzner - For: Tahkenitch Tree Farm - Aug. 1994 - M120-75 A-D and C.S. File 63/145

Found - 2½" Brass cap properly marked on 2" iron pipe with 1½" iron pipe lying along side. (C.S. 58/140)
20" Hemlock, with healed face and tag bears S.13°W., 40.2 ft.
15" Spruce, with healed face and tag bears N.50°30'W., 53.8 ft.
48" Fir stump, bears N.78°E., 1.0 ft. to face.
Bearing Object - An iron fence post bears N.66°E., 1.2 ft.

Found OK by C. Mulkins, July 1997 - M 127-39
Found OK by T. Rambo, April 2002 - M140-7