

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 12 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 11)

Set ¼ sec. post, from which
A Vine Maple 4" dia., bears N.82°E., 10 lks. dist.
A Fir 30" dia., bears N.38°W., 65 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 111-12)

1/4 Sec. cor. bet. secs. 7 and 12, which cor. I reestablish by setting a post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼ S on W. face; from which
A Fir 30" dia., bears N.38°W., 65 lks. dist. mkd. ¼ S BT, old bearing tree.
A Vine Maple 4" dia., bears S.83½°E., 13 lks. dist. mkd. ¼ S BT, new bearing tree.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 69-70)

The ¼ sec. cor. on the E. bdy. of Sec. 12. Corner gone, witness trees standing and agree with notes of same furnished by the surveyor general.
Set a Fir post at point for corner, 4 ft. long, 4" sq., 24" in the ground, mkd. S7 ¼ S on the E. and S12 ¼ S on the W. faces.
This cor. is found to be N.5°33'E., 49.73 chs. from the cor. of secs. 12 and 13.

Survey by G.R. Lecklider - For: Mrs. M.A. Patrick - Feb. 1958 - M 8-38

Found - Fir stump, N.38°W., 43.0 ft. (old face, little scribe visible.)
Set 1" Bolt, from which
38" Fir, N.72°W., 65.2 ft.
6" Hemlock, South, 69.4 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron - March 30, 1970 - C.S. File 53/66-97

Found - Old 1" bolt, badly rusted and BTs by Lecklider.
38" now 40" Fir, alive, N.72°W., 65.2 ft., lower blaze healed, upper blaze nearly healed.
6" now 12" Hemlock, alive, South 69.4 ft., blazes healed. (Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 12 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
T20S R12W R11W
¼ S12 |
1970

This cor. lies 20 ft. North of creek bottom approx. 350 ft.
East of very old, unusable logging road.
Found only badly decayed remains of stump of orig. BT.

Fd. OK July 1988 by D. Baker - M 106-67
FD. OK June 1996 by R. Ward - M 125-12
Fd. Ok by T. Rambo, 1/2002 - M 139-69