

PRIMARY CORNER DESCRIPTION SE Cor. Samuel Hall DLC #37

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,  
dated June 8, 1857 - DLC Volume, Page 4

-----  
Set post SE cor., from which  
A Fir 12" dia., bears N.88°W., 175 lks.  
A Fir 18" dia., bears S.83°W., 260 lks.

Survey by Bruce Shaner - For: Mt. Baldy Lumber Co. - March  
21, 1962 - M 23-25

-----  
Found - Orig. D.Fir Bt, stump, now 44" with scribed "#"  
visible on orig. face, later scribes on outer  
surface show "C 3" +. Stump faces S.88°E.  
measured from old face, S.88°E., 115.5 ft.

Set 1" x 30" alum. pipe, from which a:  
16" D.Fir bears N.23°W., 6.6 ft. scribe DLC 37.  
14" D.Fir bears S.35°E., 12.9 ft. scribed DLC 37.

The pipe is also at an old fence corner, the fence running N.  
and S.

Ron Rice - For: Weyerhaeuser Co. & Beckley Timber LLC -  
6/2016 - M172-21

-----  
Found - No monument found, corner falls in west side of  
abandoned dirt road. Accessories found per M23-25

New - Reset corner monument at distance-distance  
intersection face measure ( side center did not  
produce an intersection) from bearing trees  
established in M23-25.

Set - 5/8"x30" rebar with 2-1/2" aluminum cap marked:

T21S R4W  
SE DLC 37

2016  
54633LS

29" D.Fir stump bears N.23°W., 6.6' - healed face,  
M23-25

14" D.Fir stump bears S.35°E., 12.9' - axe work  
visible M23-25

44" D.Fir stump bears N.88°W., 115.5' - to rotted  
face 1857 GLO

New BTs- 11" D.Fir bears N.80°W., 16.4' - blazed, scribed SE  
DLC 37 BT

14" D.Fir bears N.26°E., 23.3' - blazed scribed SE  
DLC 37 BT

Steel post adjacent to corner.

