

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 789)

Set ¼ sec. post, from which
A Fir 20" dia., bears N.19°E., 80 lks. dist.
A W.Oak 6" dia., bears N.8°W., 55 lks. dist.

O.F. Thiel - For: Geo. Wood - March 16, 1904 - C.S. File 64/48

At 40.04 chs., intersect W. of ¼ cor., 44 lks.
Both trees dead. Marked:
White Fir 10", S.49°W., 23 lks.
Fir 7", N.22°E., 45 lks.

O.F. Thiel - For: N.M. Ohrling - May 1922 - F.B. 115 Pg. 145

One old bearing tree marked by former survey standng.
Marked- A new tree, Fir 12" S.58°W., 67 lks. (fence post at corner)

B.H. McGillucuddy - July 1953 - C.S. File 41/182

Set 3/4" iron pipe. No original BTs found.
Set new BTs:
24" Fir N.10°25'W., 84.6 ft.
22" Fir N.14°30'E., 37.9 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm Stoffel, crew - Oct. 27, 1964 - C.S. File 49/68-22

Found - 3/4" Iron pipe, top approx. 12" above ground.
20" Fir stump N.14½°E., 37.9 ft. (to face) good scribing visible.
24" Fir stump N.10½°W., 84.6 ft., good scribing visible "BT"
DID NOT SET BRASS CAP.
New BTs- 16" D.Fir S.87½°W., 29.4 ft. mkd. ¼ S36 CS BT.
5" W.Fir S.83½°E., 18.0 ft. mkd. ¼ S31 CS BT.
An old fence corner, fences N. and E., bears N.40°W., 8 ft.
Corner is approx. 300 ft. South of power line.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T21-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson; Garry L. Moore, Cadastral Surveyors and Garry L. Moore, Surveying Technician - Under Group #1406, Surveyed Feb. 2, 1988/Jan. 6, 1989 - (DCSO records Vol. 48 Page(s) 18602-03)

The ¼ sec. cor., reestablished and recorded by McGillicuddy in 1953 and further perpetuated and recorded by Godfrey in 1964.

There is no remaining evidence of the original corner, and this position is accepted as the corner; monumented with an iron pipe, ¾" dia., firmly set, projecting 12" above ground, from which the remaining bearing tree mkd. by Godfrey:

A Fir 18" dia., bears S.83½°E., 28 lks. dist. with healed blaze.

At the corner point

Set a stainless steel post 28" long, 2½" dia., 22" in the ground with brass cap mkd:

T 21 S
R 5 W R 4 W
¼
S 36 | /s 31
1988

from which new bearing trees:

A Fir 14" dia., bears S.24°E., 19 lks. dist. mkd. ¼ S31 BT

A Fir 13" dia., bears N.46½°W., 28 lks. dist. mkd. ¼ S36 BT.

Deposit Iron pipe alongside and white "DEEP-1" magnetic marker at base of stainless steel post.

Martin C. Stewart - For: Shiloh Forestry Inc. - Oct. 31, 1989 - C.S. File 63/85-43

Found - Found disturbed, a BLM 1988 brass cap on a 2" alum. pipe. Shiloh logging operation had pushed monument in a NE. direction.

Also found, BT stumps with tags and scribes visible on the NW. & SE. BTs and healed blaze on E-SE BT. All stumps have alum. sheets covering them:

4 ft. high 20" W.Fir stump bears S.83½°E., 18.0 ft. healed blaze.

4 ft. 15" D.Fir stump bears S.22°E., 12.6 ft. Placed LS2057 brass shiner in lower portion of blaze.

4 ft. high 13" D.Fir stump bears N.46½°W., 18.5 ft. Placed LS2057 brass shiner in lower portion of blaze.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

I excavated the found BLM monument and found a 3/4" x 34" galv. Iron pipe inside of monument. I was able to reestablish GIP position as it was set 3 to 4" deeper than BLM monument. I straightened both monuments and reset accordingly. No new accessories marked, as stumps should perpetuate corner position until suitable trees can be used, I painted and re-tagged BT stumps. The 1/4 corner is located within a clear-cut approx. 150 ft. West of a Guistiana Logging road on a NW. aspect.

Found OK by Les Roberts, April 2000 - M134-66