

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25, T21-5

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 789)

Set ¼ sec. post, from which
A Fir 12" dia., bears S.20°E., 25 lks. dist.
A Fir 10" dia., bears S.37°W., 82 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Mpv/ 1064 - C.S. File 49/68-29

Found - Old Fir stump, S.37°W., 54.1 ft., cut open and found good scribing.
38" old Fir stump, S.20°E., 16.5 ft., shows very good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T21S
R5W ¼ S25|S30 R4W
1964

New BTs- 11" D.Fir S.78°W., 6.8 ft. mkd. ¼ S25 CS BT.
12" D.Fir S.54°E., 3.3 ft. mkd. ¼ S30 CS BT.

Remnants of old fence lines extend North & East from corner.

Fd. OK, Feb. 1981 by R. Kimberling - M 79-69

Fd. & used on BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20390)

Fd. BC & 2 BTs by Carl Sweeden, 5/2006 - M150-52, M150-64, & 2006-0055

David Edwards - For: Beckley Timber LLC - July 2019 - M175-75

Fd - Brass cap
23" dia., Fir bears S.55°E., 3.3'
12" dia., Fir bears S.78°W., 6.6' Both w/healed blaze
Set - 6 ft. steel post 2 ft south.