

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; and 12, T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 787)

Set ¼ sec. post, from which
A Fir 6" dia., bears S.43°E., 33 lks. dist.
A Fir 3" dia., bears S.32°W., 18 lks. dist.

O.F. Thiel - For: John L. Cline - July 10, 1922 - Field Book 115 Pg. 148 (also Page #146-A)

Cut in SW. tree and found old marks. SE tree gone. Remarked SW. tree.

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15016-17)

The ¼ sec. cor. of secs.7 and 12, perpetuated by person(s) unknown, monumented with an iron pipe ¾" dia., firmly set, protruding 12" above ground, from which the remains of the original bearing trees:

A root hole and Fir roots, bears S.43°E., 33 lks. dist.
A decayed Fir stump size indeterminate, bears S.52°W., 18 lks. dist., no marks visible.

and a bearing tree of no record:

A sawed Fir stump 48" dia., bears N.15°E., 43 lks. dist., with scribe marks ¼ S7 BT visible on weathered bark blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4
S 12 | S 7
T 21 S
R 5 W R 4 W
1961

from which new bearing trees:

A Fir 10" dia., bears N.56°E., 29 lks. dist. mkd. ¼ S7 BT

A Fir 9" dia., bears S.24°W., 20 lks. dist. mkd. ¼ S12 BT

Deposit iron pipe alongside the iron post.

Survey by Les Roberts - For: Seneca Timber Co. - June 1990 - M 110-25

No corner monument found. Could not find 1971 BLM cap. Found - ¾" Iron pipe down the hill 20 ft.
(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12, T21-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Reset 3/4" iron pipe using 1971 found BLM BTs:
48" Fir stump N.16°E., 25.8 ft. No marks, unknown origin.
10" Fir S.23°W., 13.2 ft. Scar visible. 1971 BT.
15" Fir N.56°E., 19.1 ft. Scar visible. 1971 BT.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2762, surveyed May/June 2015 - (DCSO records Vol. 58 Page 23474)

The ¼ sec. cor. of secs. 7 & 12, on the W. bdy. of the Tp., perpetuated by Roberts, in 1990, monumented with an iron pipe, ¾" dia., firmly set, projecting 5" above ground, from which the remains of a BT of no record, reported by Peterson and Berry in 1971-72

A fir stump, 48" dia., bears N.15°E., 25.9 ft., with a healed blaze. (Record, 28.4 ft.)

and the bearing trees mkd. by Peterson and Berry

A fir, 25" dia., bears N.56°E., 19.1 ft., with a healed blaze.

A fir stump, 10" dia., bears S.24°W., 13.2 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, directly over the iron pipe, with brass cap mkd.

T 21 S
R 5 W R 4 W
S 12 S 7
2015

from which

A fir, 14" dia., bears N.4½°W., 43.5 ft., mkd. ¼ S12 BT. New BTs has a 2½"x¼" magnetic nail driven at the base on right side center & has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum angle irons were driven alongside each monument.

Note: There is no remaining evidence of the iron post set by Peterson and Berry. This was also noted by Roberts.