

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 5 and 6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 781)

-----  
Set ¼ sec. post, from which  
A Fir 10" dia., bears S.72°E., 76 lks. dist.  
A Fir 6" dia., bears S.5°W., 43 lks. dist.

Douglas County Surveyors Office - James Byron and crew - C.S. File 54/14-37A - Spring, 1969 & Nov. 1969 by D.L. Daniels

-----  
Corner searched for, not found.

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15029)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd:  
T 21 S R 4 W  
1/4  
S 6 | S 5  
1972

from which  
A Fir 15" dia., bears N.4°E., 37 lks. dist. mkd. ¼ S5 BT.  
A Fir 28" dia., bears N.87°W., 44 lks. dist. mkd. ¼ S6 BT.

Fd. OK, Nov. 1992 by L. Roberts - M 116-48

BLM Dependent resurvey by Daniel N. Patterson, Cadastral Surveyor, under Group No. 2335 surveyed July/Aug. 2010 - (DCSO records Vol. 57 Page 22777 and Plat 2012-1, T21-4)

-----  
The ¼ sec. cor. of secs. 5 and 6, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.  
from which the remains of BTs mkd. by Peterson and Berry  
A fir, 28" dia., bears N.4°E., 22.7 ft., with a healed blaze. (Record, 24.4 ft.)  
A fir stump, 30" dia., bears N.87°W., 29.0 ft., with a healed blaze.  
and a new bearing tree  
A fir, 6" dia., bears N.73¾°W., 20.3 ft., mkd. ¼ S6 BT.  
NAD 1983 (CORS 96)  
Latitude: 43°46'20.43"N Longitude: 123°12'26.61"W.