

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 779)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.29°W., 93 lks. dist.
A Fir 30" dia., bears S.74°W., 126 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1969 - C.S. File 54/14-38

Found - Orig. 30" Fir, now approx. 48" burned stump, S.74°W., 83.2 ft., opened by D.L. Daniels, BLM, to face with "BT" scribe.
A hole evident in approx. location of other O. B.T.

Corner would fall at old fence corner, fence E. and S., nearly gone.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 4 W
¼ $\frac{S \ 8}{S \ 17}$
1969

New BTs- 15" D.Fir S.30°W., 32.8 ft. mkd. ¼ S17 CS BT.
18" D.Fir N.66°E., 25.4 ft. mkd. ¼ S8 CS BT.

Corner lies on very steep SW. slope in bottom of dry ravine, course SW.

Cor. Fd. and tied in BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15021)

BLM Resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson; Garry L. Moore, Cadastral Surveyors and Garry L. Moore, Surveying Technician - Under Group #1406, Surveyed Feb. 2, 1988/Jan. 6, 1989 - (DCSO records Vol. 48 Page(s) 18611) (Was also filed by BLM with County in C.S. 63/87-1

The ¼ sec. cor., monumented with an iron post, 18" long, 1¼" dia., loosely set, projecting 12" above ground with brass cap mkd. in 1969, from which the remains of an orig. BT tree:

A Fir stump 48" dia., bears S.74°W., 126 lks., no marks visible on opened blaze.

and bearing trees mkd. by Tracy in 1969:

A Fir 26" dia., bears N.64°E., 39 lks., with healed blaze. (Rec. 43 lks.)

A Fir 18" dia., bears S.29°W., 51 lks., with healed blaze. (Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

At the corner point
RESET the iron post 6" in drill hole, in solid bedrock and
add the marks RESET 1988 to brass cap.
Corner is located in the bottom of a ravine, drains SW.

Fd. OK, April 1996 by Bradsby - M 123-76

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2762, surveyed May/June 2015 -
(DCSO records Vol. 58 Page 23468-9)

The ¼ sec. cor. of secs. 8 and 17, monumented with an iron
post, 1" dia., firmly set, projecting 10" above ground with
brass cap (properly) mkd.
from which the BTs mkd. by the Douglas Co Surveyor's Office
in 1969, reported by Rogers, et al, in 1988-89
 A fir, 37" dia., bears N.64°E., 25.7 ft., with a healed
 blaze.
 A fir, 20" dia., bears S.29°W., 33.7 ft., with a healed
 blaze.

2