

PRIMARY CORNER DESCRIPTION Sec Cor for 28, 29, 32 and 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 768)</p> <p>-----</p> <p>Set post cor. of secs. 28, 29, 32 and 33, from which</p> <ul style="list-style-type: none">A Laurel 12" dia., bears S.20°E., 32 lks. dist.A Laurel 10" dia., bears N.83°E., 14 lks. dist.A Laurel 10" dia., bears N.56°W., 34 lks. dist.An Oak 8" dia., bears S.35°W., 25 lks. dist.																		
<p>W. F. Briggs - Wit: Pet Matchatte and S. Tonalee - March 16-18, 1901 - Vol. 2 Page 263 and 107</p> <p>-----</p> <p>The original BTs gone, post hole visible, made new post, to wit:</p> <ul style="list-style-type: none">A Fir 4 x 4" square 3½ ft. long, from which18" Fir bears S.7½°W., 23 lks.16" Fir bears N.45½°W., 55 lks.20" Fir bears N.67°E., 103 lks.24" Fir bears S.71°E., 194 lks. <p>Old bearing trees destroyed by fire.</p>																		
<p>Oscar Thiel - May 23, 1943 (added 6/12/2012) - FB 117 Pg. 49</p> <p>-----</p> <p>Drove cedar stake in hole of old stake set by CS</p>																		
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm Stoffel, crew - Oct. 22, 1964 - C.S. File 49/68-15</p> <p>-----</p> <p>Found - Old scribed Cedar stake, so rotten it broke off when touched.</p> <ul style="list-style-type: none">36" Fir stump S.7½°W., 15.2 ft., opened and found scribing "W" on badly charred face.Rotted remains of Fir stump N.67°E., 68.0 ft.Rotted Fir snag S.71°E., 128.0 ft. No marks left. <p>Set Brass cap at cor. mkd: County Surveyors Office</p> <table style="margin-left: auto; margin-right: auto;"><tr><td>T</td><td>21</td><td>S</td><td>R</td><td>4</td><td>W</td></tr><tr><td></td><td>S</td><td>29</td><td> </td><td>S</td><td>28</td></tr><tr><td></td><td>S</td><td>32</td><td> </td><td>S</td><td>33</td></tr></table> <p style="text-align: center;">1964</p> <p>New BTs-</p> <ul style="list-style-type: none">14" D.Fir S.55°E., 23.5 ft. mkd. T21S R4W S33 CS BT10" D.Fir N.85°E., 33.7 ft. mkd. T21S R4W S28 CS BT11" D.Fir N.7½°W., 115.0 ft. mkd T21S R4W S29 CS BT <p>No good trees near to SW. Corner is in fence corner, fences E., & NE.; and in E. edge of logging road.</p>	T	21	S	R	4	W		S	29		S	28		S	32		S	33
T	21	S	R	4	W													
	S	29		S	28													
	S	32		S	33													
<p>David Wellman - For: Summerwood Inc. - June 1999 - M 132-12</p> <p>-----</p> <p>Found - Douglas Co BC 1964, 0.6 ft above ground (cont)</p>																		

PRIMARY CORNER DESCRIPTION Sec Cor for 28, 29, 32 and 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Rotten remains N.67°E., 68 ft. - evidence of face -
rec: N.67°E., 103 lks., 1901 Briggs.
Remains of snag, S.71°E., 128 ft., rec: s.71°E., 194
lks - 1901 Briggs
36" Rotten Fir stump, S.7½°W. 16.4 ft to center- "W"
scribe visible -rec: S.7½°W., 23 lks. 1901 Briggs
30" Rotten stump, N.45½°W., 36 ft. - rec: N.45½°W.,
55 lks. - 1901 Briggs
12" Fir snag, N.87°E., 34.0 ft. to spike set side
center - visible scribe - rec: N.85°E., 33.7 ft.,
1964 Douglas Co.
18" Fir stump - 3 ft. high, S.53°E., 24.0 ft. to
spike set side center - closed face - rec:
S.55°E., 23.5 ft., 1964 DCSO
11" Rotten Fir stump, N.10½°W., 116.9 ft. to center
- evidence of closed face - rec. N.7½°W., 115.0
ft., 1964 DCSO
Set - 8" Fir, S.42½°W., 32.6 ft. to spike set side center
scribed "S32 BT"
16" Fir, N.89°W., 35.8 ft. to spike set side center
scribed "S29 BT"
Note - Corner lies in Northeast/East fence line and in
easterly cutbank of dirt road.

Greg Lang - 12/2010 - C.S. File 65/69-65

Found - The DCSO brass cap was found out of the ground and
BTs as follows:
13" fir snag (1964) bears N.86½°E., 33.8 ft
15" fir stump (1964) bears S.52½°E., 23.5 ft
12" fir (1999) bears S.43°W., 32.6 ft
19" fir (1999) bears N89°W 35.8 ft
See 1999 renewal for additional information about
older tree remains.
New - We found a DCSO brass cap out of the ground. We
reset said cap by using record distances from
spikes we found in the base of the existing
bearing trees, snag, and stump.
28" fir bears N.79°E., 34.3 ft scribed "S28 BT"
12" fir bears N.64°W., 30.2 ft scribed "S29 BT"
(20d nails are set in the side center of these
two trees at the distances shown)
Note - Corner is at a fence corner and on the East cut bank
of a dirt logging road. Fences run East & NE.

continued next page

2

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec Cor for 28, 29, 32 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Daniel Baker - For: Seneca Jones Timber - 5/2019 - M176-1

- Found - 2½" Douglas Co. brass cap "1964"
27" Fir stump, N.79°E., 34.4' to center (record N.79°E., 34.3') CS FILE 65/69-65 BT
13" Fir snag, N.85°E., 33.6' to center (record N.85°E., 33.7) 1964 Douglas Co. BT
19" Fir stump, S.54°E., 23.8' to center (record S.55°E., 23.5) 1964 Douglas Co BT
11" Fir stump, S.42°W., 32.9' to center (record S.42½°W., 32.6) M132-12 BT
19" Fir stump, N.89°W., 36.5' to center (record N.89°E., 35.8') M132-12 BT

Note - No trees to north of corner-recent clearcut