

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GL0 survey by Harvey Gordon & Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 2 Page(s) 769)

-----  
Set 1/4 sec. post, from which  
A Fir 10" dia., bears S.5°E., 37 lks. dist.  
A Fir 12" dia., bears N.10°W., 50 lks. dist.

Douglas County Surveyors Office - Milo Godfrey and crew - C.S. File 49/68-31 - Nov. 5, 1964

-----  
Corner searched for, not found.  
Found squared stake, rotted off, and 3-way fence cor. No BTs found, no record of renewal.

William Eimstad - For: Charles Booher - Dec. 1979 -M 82-14

-----  
Set 3/4" Rebar, from which  
17" Fir bears N.71°E., 70.7 ft. scribed "1/4 S28 BT"  
16" Fir bears S.44°W., 7.9 ft. scribed "1/4 S33 BT"  
1/4 corner proportioned in by survey.

L. Roberts - For: Nathan Nash - Oct. 1994 - M 121-1

-----  
CONDITION REPORT ONLY  
Found - 3/4" iron pin set in survey M82-14  
20" Fir, N.70°E., 70.5' (scar vis.) 1979 BT  
20" Fir, S.44°W., 8.0 ft. (scar vis.) 1979 BT

David Wellman - For: Summerwood Inc. - June 1999 - M 132-12

-----  
Found - 5/8" iron rod per M82-14 & M84-75, 0.1 ft. above ground  
28" Fir, N.71°E., 20.4 ft. to nail set side center - closed face - rec: N.71°E., 70.7 ft. 1979 M82-14  
24" Fir, S.44°W., 7.7 ft. to nail set side center - closed face - rec: S.44°W., 7.9 ft. - 1979 M82-14  
Note - Corner lies 7 ft. east of North/South fence.

Daniel Baker - For: Seneca Jones Timber - 5/2019 - M176-1

-----  
Found - 5/8" iron rod per M82-14 and M84-75  
35" FIR, N.71°E., 20.6' to center (rec N.71°E., 20.4') M132-12 (rec N.71°E., 70.7' per M82-14  
28" Fir, S.45°W., 7.6' (rec S.44°W., 7.9' M82-14 BT  
New - 11" Fir, S.46°E., 43.4' to nail side/center-scribed "1/4 S33 BT"  
7" G.Fir, N.27°W., 10.3' to nail side/center-scribed "1/4 S28 BT"