

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 763)

Set post cor. of secs. 27, 28, 33 and 34, from which
A Fir 60" dia., bears S.45°W., 34 lks. dist.
A Fir 60" dia., bears S.75°E., 28 lks. dist.
A Fir 20" dia., bears N.45°E., 29 lks. dist.
A Fir 24" dia., bears N.40°W., 20 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - June 26, 1958 - C.S. File 49/68-4

Found - Orig. 24" now 42" R.Fir (now stump only) N.40°W., 13.2 ft. I open near base and find good scribing "BT".

I also find base of large Fir that checks bearing and distance for orig. SW. BT.

No trace of other BTs found.

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S R 4 W
S 28 | S 27
S 33 | S 34
1958

(Thiel has bark scribed the orig. NW. BT, "W BT.")

New BTs- 12" R.Fir bears S.74°W., 7.6 ft. scribed.

6" R.Fir bears N.71°E., 21.0 ft. scribed S27 CS BT.

8" R.Fir bears S.49°E., 55.3 ft. scribed S34 T21S R4W CS BT.

9" D.Fir N.61°W., 28.0 ft., (not recorded, found Oct. 1964 by M. Godfrey C.S. 49/68-23)

Glen McChesney - For: Weyerhaeuser Co. - April 10, 1961 - C.S. File 53/104-3

Found - 1855 post gone.
Rotted remains of large Fir stump (S.45°W., 34 lks.)
38" Fir stump scribed "BT" visible (24" Fir N.40°W., 20 lks.)

SE. and NE. original BTs, gone.

1958 BT, 4" Fir N.70°E., 20.8 ft., scribed.

1958 BT, 12" Fir S.48°E., 54.5 ft., scribed.

1958 BT, 14" Fir S.70°W., 7.3 ft., scribed.

1958 BT, 8" Fir N.63°W., 28.0 ft., scribed.

Accessories added:

14" Fir, N.64°E., 27.1 ft. with "W" nail/plate.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

| |
|--|
| <p>12" Fir S.49°E., 54.4 ft. with "W" nail/plate. (1958 BT) 14" Fir S.69°W., 7.0 ft. with "W" nail/plate. (1958) 38" Fir stump N.48°W., 13.6 ft. with "W" nail/plate. (1855 BT)</p> |
| <p>Cor. Fd. and used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1026, surveyed July 1980/March 1981 - (DCSO recs Vol 44 Pg 16961)</p> |
| <p>Found OK by D. Edwards, July 2002 - M140-43</p> |
| <p>BLM dependent resurvey by Harvey M. Christensen, LS 2603, under group # 2171, surveyed Nov. 2007/Aug. 2008 - (DCSO records Vol. 55 Page(s) 21532-3)</p> <p>-----</p> <p>The cor. of secs. 27, 28, 33, & 34, perpetuated by Byron, in 1958, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree A sawed fir stump, 42" dia., bears N.46°W., 14.9 ft., no marks visible. and the remains of bearing trees mkd. by Byron A fir, 9" dia., bears N.70°E., 20.8 ft with a healed blaze A decayed and sawed fir stump, 15" dia., bears S.49°E., 54.8 ft. with a healed blaze. A fir, 29" dia., bears S.71°W., 7.6 ft with a healed blaze A sawed fir stump, 15" dia., bears N.61½°W., 28.4 ft., with a healed blaze. and the remains of a BT mkd. by McChesney, in 1961 A sawed fir stump, 18" dia., bears N.64°E., 27.1 ft., with a healed blaze. and a new bearing tree A western hemlock, 9" dia., bears S.76¾°E., 21.0 ft., mkd. T21S R4W S34 BT. Set 5 ft. steel fence post alongside cor. Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description</p> |
| <p>Daniel Baker - For: Seneca Jones Timber - 5/2019 - M176-1</p> <p>-----</p> <p>Found - 2½" Douglas County brass cap "1958" 17" Fir stump, N.62°E., 27.0' to center (rec N.64°E., 271)-1961 Weyerhaeuser BT 11" Fir, N.69°E., 20.9' to center (record N.70°E., 20.8)-1958 Douglas County BT</p> <p>continued next page</p> |

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

| |
|---|
| <p>12" Hemlock, S.77°E., 21.0' to center (rec S.76¾°E., 21.0)-2008 BLM BT</p> <p>12" rotten fir stump, S.48°E., 54.8' to center (record S.48°E., 54.5)-1958 Douglas Co. BT</p> <p>34" Fir, S.70°W., 7.6' to center (record S.70°W., 7.3')-1958 Douglas Co. BT</p> <p>15" Fir stump, N.63°W., 28.4' to center (record N.63°W., 28.0)-1958 Douglas Co BT</p> <p>38" Fir stump, N.44°W., 15.0' to center (record N.40°W., 20 lks.)-original BT</p> |
| |