

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 2 Page(s) 765)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 8" dia., bears N.82°E., 47 lks. dist. A Fir 4" dia., bears N.80°W., 21 lks. dist.</p>
<p>Oscar Thiel - For: Perkins and Bledsoe - Jan. 8, 1902 - Field Book 113 Pg. 115</p> <p>-----</p> <p>Set Dogwood post on E. slope.</p>
<p>Douglas Co. Surveyors office - James Byron - Aug. 1, 1958 - C.S. File 49/68-7</p> <p>-----</p> <p>Found 1" I.Pipe set Fir corner. A 24" partly rotted Fir stump, bears N.48°W., 8.3 ft., shows faint scribe marks on old face "T". A 34" partly rotted Fir stump bears S.61°W., 14.9 ft. shows faint scribe marks "BT". Old N-S wire fence 16.4 ft. West. Note: I believe this corner was renewed by Thiel 25 years ago. Call South to creek checks OK. i find no trace of orig. BTs found.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Oct. 1964 - C.S. file 49/68-23</p> <p>-----</p> <p>Looked for, not found.</p>
<p>Found I.P., no identifiable BTs. July 1953 by Charles Bayles - C.S. File 41/183</p>
<p>Survey by William Eimstad - For: J.H. Baxter Co. - Oct. 1981 - M 89-25</p> <p>-----</p> <p>Set 5/8" x 30" Re-bar at corner, from which 10" Fir bears N.38°E., 16.4 ft., scribed ¼ S22 BT. 18" Fir bears N.74¼°W., 64.6 ft. scribed ¼ S21 BT. Found 1" Pipe bears S.40°58'W., 12.29 ft., no acceptable evidence in DCS0.</p>
<p>Fd. I.R., Jan. 1993 by R. Dolan - M 116-4</p>
<p> </p>