

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34 of T20-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 748)

Set ¼ sec. post, from which
A R.Fir 8" dia., bears S.36°W., 38 lks. dist.
A R.Fir 6" dia., bears N.10°W., 45 lks. dist.

BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt; Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed Aug. 1970 - (DCSO records Vol. 37 Page(s) 15277)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 20 S R 4 W
¼ $\frac{S\ 34}{S\ 3}$
T 21 S
1971

from which
A Fir 6" dia., bears S.34½°E., 25½ lks. dist. mkd. ¼ S3 BT.
A Fir 8" dia., bears S.79½°W., 40 lks. dist. mkd. ¼ S3 BT
Set a 6 ft. steel fence post alongside iron post.

BLM resurvey by Daniel N. Patterson and Craig L. Wanless, Cadastral Surveyors, Under Group #1705, Surveyed Aug/Oct. 1993 - (DCSO records Vol. 51 Page(s) 19250-51)

The ¼ sec. cor. monumented with an iron post 2½" dia., firmly set, projecting 4" above the ground with brass cap mkd. in 1971,
from which the remains of bearing trees mkd. by Brooks, etal
A root hole bears S.34½°E., 28½ lks.dist. alongside of which is lying a Fir, 8" dia., with healed blaze. (Rec. 25½ lks.)
A Fir 14" dia., bears S.76 3/4°W., 41 lks. dist., with healed blaze.
and a new bearing tree
A Fir 15" dia., bears S.25½°E., 65 lks. dist. mkd. ¼ S3 BT
No suitable tree available in sec. 34.