

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 757)

-----  
Set ¼ sec. post, from which  
A Fir 10" dia., bears N.40°E., 25 lks. dist.  
A Fir 8" dia., bears S.87°W., 12 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Dec. 4, 1957 - C.S. File 49/42-1

-----  
Found - Orig. 8" now 6" snag, partly rotted Fir, S.87°W. 7.9 ft. Has open face, good scribing "¼S"  
I can find no trace of orig. NE. BT.  
Set ¾" Iron rod at corner.  
New BTs- 12" W.Fir N.29°W., 37.0 ft. scribed ¼ S34 CS BT.  
17" Cedar N.80½°E., 57.5 ft. scribed ¼ S35 CS BT.

Glen McChesney - For: Weyerhaeuser Co. - April 30, 1958 - C.S. File 53/104-5

-----  
Found - No trace original 1855 post.  
No trace orig. Fir, NE.  
8" Fir S.87°W., 12 lks., found 10" down stub, has been dead many years. Scribing visible.  
Probably Doug. Co., 10" Fir scribed "¼ S34 CS BT" about 6 months old. N.30°W., 36.4 ft.  
Accessories Added:  
10" Fir N.30°W., 36.4 ft. with "W" nail/plate. (1957 BT)  
36" W.Fir S.75°W., 35.6 ft. with "W" nail/plate.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1026, surveyed July 1980/March 1981 - (DCSO records Vol. 44 Page(s) 16957)

-----  
The ¼ sec. cor., perpetuated and recorded by Byron in 1957, monumented with an iron rod, 5/8" dia., firmly set, projecting 8" above ground, from which the remains of an original bearing tree:  
A root hole bears S.87°W., 12 lks. dist., with a down Fir alongside, 5" dia., with fragmentary scribe marks visible on open blaze.  
and bearing trees mkd. by Byron:  
A Cedar 25" dia., bears N.80°E., 86½ lks. dist., with healed blaze.  
(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 34 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A grand Fir 18" dia., bears N.32°W., 55½ lks. dist., with healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 21 S R 4 W

1/4

S 34 | S 35

1980

from which new bearing trees:

A Grand Fir 6" dia., bears S.69°E., 10 lks. dist., mkd. ¼ S35 BT.

A Fir 6" dia., bears N.62°W., 19 lks. dist. mkd. ¼ S34 BT.  
Reset Iron rod alongside the iron post.

Survey by Don Peel - For: Weyerhaeuser Co. - July 13, 1988 - M 106-48

-----  
CORNER REPORT ONLY

Found - US BLM 2½" Iron pipe with brass cap dated 1980, 3/4" rebar alongside.

27" Cedar N.81°E., 57.0 ft., closed face.

8" W.Fir S.69°E., 6.3 ft., closed face.

9" Fir S.63°W., 12.6 ft., closed face. (Rec. N.62°W)

19" W.Fir N.30 3/4°W., 36.1 ft., closed face.

BLM dependent resurvey by Harvey M. Christensen, LS 2603, under group # 2171, surveyed Nov. 2007/Aug. 2008 - (DCS0 records Vol. 55 Page(s) 21528)

-----  
The ¼ sec. cor. of secs. 34 and 35, monumented with an iron post, 2½" dia., firmly set, projecting 3" above the ground (alongside of which is an iron rod, 5/8" dia., firmly set, projecting 2" above ground), with brass cap (properly) mkd. from which bearing trees mkd. by James Byron, in 1957

A cedar, 28" dia., bears N.80°E., 57.1 ft., with a healed blaze.

A G.Fir, 26" dia., bears N.32°W., 36.6 ft., with a healed blaze.

and bearing trees mkd. by Jelley and Rogers

A G.Fir, 10" dia., bears S.69°E., 6.6 ft., with a healed blaze.

A D.Fir, 13" dia., bears S.62°W., 12.5 ft., with a healed blaze. (Record, N.62°W.)

Set 5 ft. aluminum fence post alongside cor.