

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 760)

Set post corner of secs. 10, 11, 14 and 15, from which
A Hemlock 10" dia., bears N.10°E., 17 lks. dist.
A Hemlock 8" dia., bears S.18°E., 27 lks. dist.
A Cedar 8" dia., bears S.45°W., 16 lks. dist.
A Cedar 10" dia., bears N.75°W., 16 lks. dist.

On State Hwy. Map filed as F-4, dated May 1951, states, "Found capped 2" Pipe".

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 20, 1968 - C.S. File 54/14-34

Nothing found. Logged and cleared many years ago.

Survey by Donald Peel - For: Weyerhaeuser Co. - Oct. 1990 - M 110-72

Set 2" x 41" Iron pipe with brass cap and 6 ft. steel fence post 2 ft. South, from which
11" Fir N.71°E., 114.2 ft. scribed "T21S R4W S11 BT"
23" Fir S.76½°E., 118.3 ft. scribed "T21S R4W S14 BT"
18" Maple S.41°W., 33.0 ft. scribed "T21S R4W S15 BT"
18" double Alder, N.13°W., 46.5 ft. scribed "T21S R4W S10 BT"

Fd. OK, April 1996 by L. Roberts - M 123-56
Found OK by D. Crowe, Nov. 2002 - M141-38

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 6/17/2003 - C.S. File 66/58-13

Found 1990 brass cap/iron pipe.

Search made for 2" capped IP as noted by OSHD in 1951. (F-4)
Found 2" outside dia., by 48" long capped iron pipe layed over on side 2 ft. underground. Appears to be displaced, no position determinable.
From uncapped end (uphill, easterly end) of found IP, 1990 BC/IP bears N.30½°E., 50.6 ft.
13 ft. East of N-S drainage.
No OBTs fd.
1990 BTs not check
See last Pg for pictures.

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. ok by Wm. Eimstad, 4/2004 - M145-67
FD. Ok by Kris DeGroot 10/2006 - M146-46A

Edward Brown - For: Fruit Growers Supply Co. - 9/2023 - M182-67

Found - 2" Brass cap and iron pipe.
24" Fir, N.71°E., 114.2' to nail in face
31" Maple, S.41°W., 33.0' to nail in face
20" Alder, N.13°W., 46.5' to nail in face
Metal "T" post bears north 1.0'



