

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 760)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.52°W., 42 lks. dist.
A Fir 24" dia., bears N.38°W., 33 lks. dist.

Geary H. Worth, Transitman - For: Oregon State Hwy. Commission - June 1, 1951 - C.S. File 54/14-52

By single proportionate measurement.
There being no trace of original corner or Bts, I SET a 1/2" I.P., 8" out of ground at point, from which a 15" Cedar bears S.33°10'W., (grid) S.28°45'W. (mag.) 296.0 ft. There being no living trees available in sec. 14, I cause a mound of large basalt quarry rock to be built with its South edge 6" North of I.P. Said mound is 2 ft. x 2½ ft. base by 1½ ft. high.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 20, 1968 - C.S. File 54/14-34

Found 1/2" I.R. and mound of stone 2.0 ft. North. No O.B.T.s or new BTs. Cor. falls in rock quarry. Apparently set by O.S.H.D., unrecorded.

BLM Resurvey by Lester E. Fischer, Cadastral Surveyor, Under Group #1130, Surveyed Nov./Dec. 1982 - (DCSO records Vol. 46 Page(s) 17606-07)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron rod, 24" long, 5/8" dia., 22" in the ground.
No suitable trees available.
Set a 5 ft. steel fence post alongside iron rod.
Corner is located in rock quarry where it is impracticable to establish a standard monument.

Harvey Christensen - For: Freres Lumber Co. & Willamette Industries - Aug. 20, 2000 - M 143-29 (Filed in Douglas Co. 11/19/2003 - filed in Lane Co. 9/22/2000)

Found - RM to ¼ cor. not fd.
1982 BT to RM for ¼ Secs. 14/23:
22" W.Hemlock S.15°W., 88.10 ft. healed face.

continued next page

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At corner fd:

5/8" rebar, 0.25 ft. above ground.

5/8" rebar N.89°E., 20.8 ft. W/ODOT sign near by.

Note - RM & ¼ corner lay in ODOT stock pile site.

Found OK by H. Christensen, Oct. 2003 - M143-28