

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 761)

Set ¼ sec. post, from which
A Fir 50" dia., bears N.5°W., 88 lks. dist.
A Fir 40" dia., bears S.43°W., 65 lks. dist.

Crew - Anderson, instrument; Worth, notekeeper; Prichard & Andrus, Chain. - Nov. 16, 1950 - C.S. File 54/14-51 & State Hwy Map F-4

¼ cor. sec. 11/14 (identified by 2 bearing trees in notes (now stumps) & 2 new trees, A 10" Fir app. 9' SE & an 8" Fir app. 17' N.80°W.)
App. 2' N. of intersecting fence lines N, S, E & W, a 1" I.P.

State Hwy. Maps filed as F-4, dated May 1951; and N-4, dated July 1977, "find 1" pipe, 2 old BTs stumps & 2 new BTs & fence corner."

Survey by Donald Peel - For: Weyerhaeuser Co. - Oct. 1990 - M 110-72

CORNER REPORT ONLY
Found - 5/8" Rebar.
21" Fir S.63 3/4°E., 13.7 ft., closed face.
48" Fir stump S.43½°W., 42.9 ft., scribing visible on pitch face "BT".
1" (O.D.) iron pipe bears N.66°01'40"E., 5.73 ft.

Found OK by K. Hoffine, June 2000 - M135-35 A&B
Fd. ok by Wm. Eimstad, 4/2004 - M145-67