

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 762)

Set ¼ sec. post, from which
A Fir 18" dia., bears S.40°E., 22 lks. dist.
A Fir 8" dia., bears N.5°W., 20 lks. dist.

Oscar Thiel - March 1899 - Vol. 2 Page 261

Set a Cedar post, from which a
Fir 20" dia., bears N.44°E., 25 lks. dist.
A Cedar 12" dia., bears S.2°E., 32 lks. dist.
Found only one stump of one original BT, part of letters still visible.
In presence of D. Perini and Lane Co. Surveyor, C.M. Collier, Jan. 25, 1899

Douglas Co. Surveyors Office - Vic Cangie; Michael Thompkins, crew - Oct. 26, 1976 - C.S. File 59/24-46

Found - 3/4" pipe 8" above ground, not of record.
Three corner posts lying beside pipe.
Found no trace of bearing trees.
BLM location post on 16" Fir, 5 ft. NE. of pipe.
Pipe lies on old E-W blazed line. Pipe is not of record.
WE DO NOT SET CORNER FOR LACK OF EVIDENCE.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 25, 1983 - C.S. File 62/9-1

CORNER VISITATION REPORT ONLY
Found - 3/4" iron pipe, 8" above ground, source unknown.
1/2" Iron pipe set by property owner, Pfeiffer. (not of record)
Found decayed Fir stump, indeterminate dia., bears S.40°E., 14.5 ft. from 1/2" I.P. Possible orig. 18" dia. Fir.
Found Fir stump 31" dia., bears N.44°E., 16.5 ft. from 1/2" I.P. Possible 20" Fir per Thiel.
Found Cedar stump, 24" dia., bears S.2°E., 21.1 ft. from 1/2" I.P. Possible 12" Cedar per Thiel.
Mr. Herman Pfeiffer, property owner, had set 1/2" Iron pipe off of stumps he believes are BTs from Thiel. He ran line between secs. 2 and 11 and said distances fit well.
All dists taken on this visit were to poss. face of stumps.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Les Roberts, LS #1039 - For: Herman Pfeiffer - Oct. 1, 1983 - C.S. File 58/229-20

Found - 24" Fir stump, bears S.40°E., 14.5 ft. to face, no marks. (1855)
32" Fir stump, bears N.44°E., 16.3 ft. to face, no marks. (1899)
28" Cedar stump, bears S.02°E., 21.1 ft. to face, no marks. (1899)

The above bearings and distances were taken from a found 1/2" iron pipe (no record) set by property owner, Herman Pfeiffer.
New BTs- 12" Fir bears N.31°W., 16.5 ft. to center. Scribed.
17" Fir bears N.71°E., 35.8 ft. to center. Scribed.

Fd. OK, Oct. 1994 - M 120-70 AND SET 1½" X 36" BRASS CAP OVER FOUND 1/2" I.P.

Fd. OK, April 1996 by L. Roberts - M 123-56
Found OK by K. Hoffine, June 2000 - M135-35 A&B
Fd. ok by Wm. Eimstad, 4/2004 - M145-67