

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

(THIS CORNER LIES IN LANE COUNTY - CHECK WITH THEIR OFFICE FOR ANY POSSIBLE INFORMATION NOT FILED WITH DOUGLAS COUNTY)

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 754)

-----  
Set post cor. of secs. 25, 26, 35 and 36, from which  
A Fir 36" dia., bears N.67°E., 35 lks. dist.  
A Fir 18" dia., bears S.58°E., 36 lks. dist.  
A Fir 40" dia., bears N.23°W., 36 lks. dist.  
A Cedar 6" dia., bears S.38°W., 4 lks. dist.

Survey by Gilbert A. Gardner - For: W.A. Woodard Lumber Co. - July/Dec. 1955 - C.S. File 42/131; M 2-16

-----  
Set at proportionate distance.  
Marked new bearing trees:  
10" D.Fir S.30°W., 13.8 ft. mkd. S35 BT.  
10" D.Fir S.8°E., 29.2 ft. mkd. S36 BT.  
10" D.Fir S.72°E., 13.9 ft. mkd. S25 BT.  
10" D.Fir N.62°W., 6.6 ft. mkd. S26 BT.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #398 Surveyed, April/May 1958 - (DCSO records Vol. 31 Page(s) 12987)

-----  
Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 21 S R 4 W  
S 26 | S 25  
S 35 | S 36  
1958

from which  
A Fir 8" dia., bears N.32°E., 48 lks. dist. mkd. T21S R4W S25 BT.  
A Fir 14" dia., bears S.55°E., 47 lks. dist., mkd. T21S R4W S36 BT.  
A Fir 10" dia., bears S.48¼°W., 19 lks. dist., mkd. T21S R4W S35 BT.  
A Fir 9" dia., bears N.16 3/4°W., 39 lks. dist., mkd. T21S R4W S26 BT.

From this point a locally established cor. bears S.35°W., 34½ lks. dist. monumented with a Fir stake, 2' sq., protruding 4 ft. above ground, firmly set, from which (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir 7" dia., bears S.72½°E., 25 lks. dist. mkd. S26 BT  
A Fir 7" dia., bears S.8 3/4°E., 45 lks. dist. mkd. S36 BT  
A Fir 10" dia., bears S.26½°W., 22 lks. dist. mkd. S35 BT.  
A Fir 10" dia., bears N.65°W., 10 lks. dist. mkd. S26 BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen  
Flause, crew - Nov. 13, 1991 - C.S. File 64/21-3

Found - No evidence of orig. or renewal from 1955 monuments  
found.

1958 BLM brass cap on a 2½" O.D. Iron pipe, firmly  
set and protruding 6" above ground.

No evidence of original BTs found.

BTs from 1955 evident but not checked. (BLM did not  
accept Gardner's corner position.)

1958 BLM BT, a Fir 8" dia., now a 15" DBH 6 ft. tall  
Fir stump with a fully healed single blaze bears  
N.32°E., 28.4 ft. (Rec. N.32°E., 31.7 ft.)  
(possible error in record links measurement)

1958 BLM BT, a Fir 14" dia., now 22" DBH 5 ft. tall  
Fir stump with a fully healed single blaze, bears  
S.55°E., 31.0 ft. (as per record)

1958 BLM BT, a Fir 10" dia., now a 16" DBH D.Fir  
with a fully healed single blaze, bears S.48¼°W.,  
12.5 ft. (as per record)

1958 BLM BT, a Fir 9" dia., now a 16" DBH 5½ ft.  
tall Fir stump with a fully healed single blaze,  
bears N.16 3/4°W., 25.7 ft. (as per record)

New BTs- 13" DBH D.Fir scribed "T21S R4W S36 CS BT" on a  
double blaze, bears S.02½°E., 3.4 ft.

22" DBHD.Fir scribed "T21S R4W S35 CS BT" on a  
double blaze, bears S.89°W., 34.0 ft.

Corner is in large clear cut with large second growth timber  
remaining in SW. quadrant. Cor. is approx. 100 ft. southerly  
from Weyerhaeuser Timber access road.