

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 037020

PRIMARY CORNER DESCRIPTION N NW cor. Samuel Hall DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,  
dated June 8, 1857 - DLC Volume, Page 3

-----  
Set post NW cor. claim 37, from which  
A Cedar 15" dia., bears S.73°E., 22 lks.  
A Fir 24" dia., bears N.75°E., 58 lks.

O.F. Thiel - For Wm. Ward Estate - Nov. 1901 - Field Book 113  
Page 112

-----  
Old bearing trees standing. Set Cedar post.

Oscar Thiel - For: J.R. Lawrence - Aug. 7, 1948 - Field Book  
5 Page 35

-----  
Trees cut down. Both old BTs gone. SE tree, Cedar stump and  
stump of NE. tree. Found ofl stake set in a survey years  
ago. This fence cor.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike  
Stone & Wm. Stoffel, crew - Nov. 1964 - C.S. File 49/68

-----  
Found - 1" Iron pipe with alum. sleeve mkd. "C37". (no  
record)  
Old Cedar stump S.73°E., 14.5 ft., W. side of stump  
gone. Evidence of old face on chips at base of  
stump, but no scribing.  
Base of old Fir stump N.75°E., 38.3 ft., not enough  
left for scribing or scars.  
Iron pipe (also old Cedar stake alongside) is in 3-  
way fence corner, fences E., W., and S.  
New BTs- 9" I.Cedar N.45½°W., 71.0 ft. mkd. NW DLC 37 CS BT.  
10" I.Cedar S.64°W., 29.0 ft. mkd. NW DLC 37 CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Dec. 1968 - C.S. File 54/14-45

-----  
Found - 1" I.Pipe and alum. sleeve mkd. "C37".  
9" now 11" I.Cedar, alive, N.45½°W., 71.0 ft.,  
scribe marks visible on healing blaze.  
10" now 11" I.Cedar, alive, S.64°W., 29.0 ft.,  
scribe marks visible on healing blaze.

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S R 4 W \_\_\_\_\_

N.W. DLC /37

1968

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION N NW Cor. Samuel Hall DLC #37

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Reset old pipe alongside brass cap. Also remains of old Cedar corner post. This cor. lies at fence corner, fences E-W and S.</p>
<p>Fd. OK, Jan. 4, 1989 by L. Roberts - C.S. File 63/85</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 24, 2013 - C.S. File 67/38-46</p> <p>-----</p> <p>Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe protruding 12" above ground. 1928 1" I.D. iron pipe with alum. sleeve (origin unknown) is loosely set protruding 12" above ground N.45°W., 1.0 ft. from above fd monument. 1964 A cedar 15" dia., now a maximum 30" dia., approx. 3 ft. tall cedar stump with most of westside missing; bears S.76°E., 13.0 ft. (rec. S.73°E., 14.5 ft.) OBT No evidence of NE OBT remains. 9" I.Cedar now a 30" dia., 3 ft. tall I.Cedar stump with no blaze evident. This stump is opened enough to show a sound face and the scribing "S". This stump bears N.44¾°W. 71.0 ft (rec. N.45½°W., 71.0 ft.) 1964 10" I.Cedar now a 12" dia., 1 ft. tall rotted I.Cedar stump with a rotted away blaze bears S.64°W., 29.0 ft. (as per record) 1964 Fences called out in 1968 renewal are down, some evidence of E-W fence remains, south running fence is gone.</p> <p>Renewed- The 1" I.D. iron pipe with an alum. sleeve is removed from ground (fd. to measure 39" long) and is reset on north edge of fd. BC monument protruding 11" above ground. A 9" dia., D.Fir scribed "NNW DLC 37 CS" "BT" on a double blaze; bears N.40½°E., 36.9 ft. A 13" dia., I.Cedar scribed "NNW DLC 37 CS" "BT" on a double blaze; bears S.68¾°E., 37.9 ft. A 10" dia., W.Oak scribed "NNW DLC 37 CS" "BT" on a double blaze; bears S.45½°W., 7.9 ft. A 19" dia., D.Fir scribed "NNW DLC 37 CS" "BT" on a double blaze; bears N.1°W., 2.7 ft.</p> <p>Note - Corner is on mild east slope in mixed age reprod D.Fir forest. Compass decl. 15½°E.</p>
<p>2</p>