

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 31 and 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 812-13)

-----  
Set ¼ sec. post, from which  
A Fir 20" dia., bears S.81°W., 110 lks. dist.  
A Fir 12" dia., bears N.28°E., 74 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Stoffel and Stone, crew - Dec. 1964 - C.S. File 49/68-59

-----  
Found - Fir, down and split open, N.28°E., 48.8 ft., good scribing visible.  
No trace of SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office  
T 21 S R 5 W  
¼ S31|S32  
1964

New BTs- 24" Madrone N.9°E., 35.4 ft. mkd. ¼ S32 CS BT.  
7" D.Fir N.44°E., 24.3 ft. mkd. ¼ S32 CS BT.  
No trees near West of line.

Fence corner, fences N., S. and E., bears South 5.5 ft.

Fd. OK, Aug. 1984 by F.O. Williams - M 97-48  
Fd. OK, Nov. 10, 1994 - M 121-24

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Feb. 4, 2014 - C.S. File 67/41-16

-----  
Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe set protruding 8" above ground.  
A fir 12" dia., now a fallen, rotted and split open 32" dia., D.fir showing an intact face with a chaining notch and the scribing "BT". The rotted and broken stump of this tree bears N.28°E., 48.8 ft. (As per rec.) OBT

No evidence remains of SW OBT

A 24" Madrone now 44" dia., Madrone with a fully healed double blaze; bears N.9°E., 35.4 ft. (as per rec.) 1964

A 7" D.Fir now a 24" dia., D.Fir with a fully healed double blaze; bears N.44°E., 24.3 ft. (as per rec.) 1964

New - An 11" dia., D.Fir scribed "¼ S31 CS" "BT" on a double blaze; bears S.28°W., 25.5 ft.

A 17" dia., D.Fir scribed "¼ S31 CS" "BT" on a double blaze; bears N.67½°W., 15.2 ft.

continued next page

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Monument is on a moderate south slope in a North-South running fence line. 5 ft. south of corner. A fallen fence runs east. Monument is in old fir reprod. forest. Most of NE quadrant was clear-cut 20± years ago.  
Compass decl. 15½°E.